



RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
1		ITEM-00001	RECTIFY PAC UNIT - 6 DEFECTS @	1	EA				
			HMLISUBSTATION NAME - HMLI 132KVSAP NUMBER						
			- 30347360PACKAGE UNIT NUMBER PU -6CARRIER;						
			MODEL # 50TJ-0						
			28-B9A3YASL # 2606U13621SCOPE:-BLOWER						
			MOTOR PULLEY SHALL BE REPLACED AND BELT						
			HAS TO BE REPLACED ANDREINSTATE THE UNIT						
			BACK TO NORMA						
			L WORKING CONDITIONBLOWER SIDE ACCESS						
			DOORS GLASS WOOL INSULATION NOT AVAILABLE,						
			SHALL BEREPLACED.CONTACT PERSON FOR SITE						
			VISIT:WA						
			RRANTY - 1 YEAR FOR WORKMANSHIP AND NEW						
			MATERIALS SUPPLIED.PAYMENT TERMS AND						
			CONDITIONS:PENALTY: THE CONTRACTOR SHALL						
			COMPLETE THIS						
			WORK WITHIN 12 MONTHS OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENTITLEDTO A REDUCTION IN THE PO						
			VALUE BY						
			1.25% PER WEEK OF DELAY AND SUBJECT						
			TOMAXIMUM 10% OF PO VALUE.RETENTION						
			AMOUNT: 5% OF THE TOTAL VALUE OF THE PO						





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WILL BE KEPT AS ARET ENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS SUPPLY AIR SENSOR WIRING NEED TO BE RE-ROUTE PROPERLY BY THECONTRACTOR.						
2		ITEM-00002	RECTIFY PAC UNIT - 5 DEFECTS @ HMLISUBSTATION NAME - HMLI 132KVSAP NUMBER - 30347359PACKAGE UNIT NUMBER PU -5CARRIER; MODEL # 50TJ-0 28-B9A3YASL # 2606U13620SCOPE:-BLOWER MOTOR PULLEY SHALL BE REPLACED AND BELT HAS TO BE REPLACED ANDREINSTATE THE UNIT BACK TO NORMA L WORKING CONDITIONBLOWER SIDE ACCESS DOORS GLASS WOOL INSULATION NOT AVAILABLE, SHALL BEREPLACED.CONTACT PERSON FOR SITE VISIT:WA RRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WORK WITHIN 12 MONTHS OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENTITLEDTO A REDUCTION IN THE PO						
			VALUE BY						
			1.25% PER WEEK OF DELAY AND SUBJECT						
			TOMAXIMUM 10% OF PO VALUE.RETENTION						
			AMOUNT: 5% OF THE TOTAL VALUE OF THE PO						
			WILL BE KEPT AS ARET						
			ENTION AMOUNT FOR 1 YEAR AFTER THE						
			COMPLETION CERTIFICATE IS ISSUED,IT WILL BE						
			RELEASED TO THE CONTRACTOR UPON CLEARING						
			ALL RELATED						
			NODS SUPPLY AIR SENSOR WIRING NEED TO BE						
			RE-ROUTE PROPERLY BY THECONTRACTOR.						
3		ITEM-00003	RECTIFY PAC UNIT - 4 DEFECTS @	1	EA				
			HMLISUBSTATION NAME - HMLI 132KVSAP NUMBER						
			- 30347358PACKAGE UNIT NUMBER PU -4CARRIER;						
			MODEL # 50TJ-0						
			28-B9A3YASL # 2606U13619SCOPE:-BLOWER						
			MOTOR PULLEY SHALL BE REPLACED AND BELT						
			HAS TO BE REPLACED ANDREINSTATE THE UNIT						
			BACK TO NORMA L WORKING CONDITIONBLOWER SIDE ACCESS						





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			DOORS GLASS WOOL INSULATION NOT AVAILABLE, SHALL BEREPLACED.CONTACT PERSON FOR SITE VISIT:WA RRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 12 MONTHS OF PORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARET ENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED						
			NODS.						
4		ITEM-00004	RECTIFY PAC UNIT - 3 DEFECTS @ HMLISUBSTATION NAME - HMLI 132KVSAP NUMBER - 30347357PACKAGE UNIT NUMBER PU -3CARRIER;	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			MODEL # 50TJ-0						
			28-B9A3YASL # 3006017237SCOPE:-BLOWER						
			MOTOR PULLEY SHALL BE REPLACED AND BELT						
			HAS TO BE REPLACED ANDREINSTATE THE UNIT						
			BACK TO NORMA						
			L WORKING CONDITIONBLOWER SIDE ACCESS						
			DOORS GLASS WOOL INSULATION NOT AVAILABLE,						
			SHALL BEREPLACED SUPPLY AIR SENSOR						
			WIRING NEED						
			TO BE RE-ROUTE PROPERLY BY						
			THECONTRACTOR.CONTACT PERSON FOR SITE						
			VISIT:WARRANTY - 1 YEAR FOR WORKMANSHIP						
			AND NEW MATERIALS SUPPLIED.						
			PAYMENT TERMS AND CONDITIONS:PENALTY: THE						
			CONTRACTOR SHALL COMPLETE THIS WORK						
			WITHIN 12 MONTHS OF PORELEASE DATE, IF THE						
			WORK IS DEL						
			AYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A						
			REDUCTION IN THE PO VALUE BY 1.25% PER WEEK						
			OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO						
			VAL						
			UE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE						
			OF THE PO WILL BE KEPT AS ARETENTION						





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE I S ISSUED, IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
5		ITEM-00005	RECTIFY PAC UNIT - 2 DEFECTS @ HMLISUBSTATION NAME - HMLI 132KVSAP NUMBER - 30347356PACKAGE UNIT NUMBER PU -2CARRIER; MODEL # 50TJ-0 28-B9A3YASL # 3006017235SCOPE:-BLOWER MOTOR PULLEY SHALL BE REPLACED AND BELT HAS TO BE REPLACED ANDREINSTATE THE UNIT BACK TO NORMA L WORKING CONDITIONBLOWER SIDE ACCESS DOORS GLASS WOOL INSULATION NOT AVAILABLE, SHALL BEREPLACEDISOLATOR CANOPY NOT AVAILABLE. SHALL BE INSTALLED BY THE CONTRACTOR.CONTACT PERSON FOR SITE VISIT:WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.PAYM ENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WITHIN 12 MONTHS OF PORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.R ETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS IS SUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
6		ITEM-00006	REPLACE BLOWER PULLEY IN PU-5 @ SRSWHSAP # 30348030SUBSTATION NAME # SRSWH 400KVZAMIL COOLINE; MODEL - PL300LDSMKNLCCBNNCSSSERIAL NU MBER - CPJBP0022MREPLACEMENT OF PACKAGE UNIT PU-5 BLOWER PULLEY AND ASSOCIATED WORKS ANDREINSTATE THE UNIT BACK TO NORMAL WORKING CO NDITION.	1	EA				
7		ITEM-00007	REPLACE BLOWER PULLEY IN PU-4 @ SRSWHSAP # 30348029SUBSTATION NAME # SRSWH 400KVZAMIL	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			COOLINE; MODEL - PL120LPSFJNNCCBNNCSSSERIAL NU MBER - CPJBP0021MREPLACEMENT OF PACKAGE UNIT PU-4 BLOWER PULLEY AND ASSOCIATED WORKS ANDREINSTATE THE UNIT BACK TO NORMAL WORKING CO NDITION.						
8		ITEM-00008	REPLACE BLOWER PULLEY IN PU-3 @ SRSWHSAP # 30348028SUBSTATION NAME # SRSWH 400KVZAMIL COOLINE; MODEL - PL120LPSFJNNCCBNNCSSSERIAL NU MBER - CPLVF0017MREPLACEMENT OF PACKAGE UNIT PU-3 BLOWER PULLEY AND ASSOCIATED WORKS ANDREINSATE THE UNIT BACK TO NORMAL WORKING CON DITION.		EA				
9		ITEM-00009	REPLACE RAD IN PAC UNIT PU-4 @ DLFFSAP - 30347121PACKAGE AC UNIT PU-4MAKE - CARRIERMODEL NUMBER - 50TJ-024-B9A3BASERIAL NUMBER - 150 8U09843PACKAGE UNIT PU-4 RAD SIZE (APPROX.)-850X890(H)MM; CONTRACTOR NEEDS TOTAKE THE ACTUAL SITE MEASUREMENTS PRIOR TO	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
			ARRANGE THE						
			MATERIALS.CONTACT PERSON FOR SITE						
			VISIT:CONTACT PERSON FROM DEWA SIDE:MR						
			THOMAS -						
			050-1615464THOMAS.JOSEPH@DEWA.GOV.AEMR.						
			ABDUL RAH						
			MAN FAHED : MOB:						
			050-						
			2166717ABDULRAHMAN.FAHED@DEWA.GOV.AEWA						
			RRANTY - 1 YEAR FOR WORKMANSHIP AND NEW						
			MATERIALS SUPPLIED.PAYMENT TERMS						
			AND CONDITIONS:PENALTY: THE CONTRACTOR						
			SHALL COMPLETE THIS WORK WITHIN 12 MONTHS						
			OF PORELEASE DATE, IF THE WORK IS DELAYED						
			BEYOND TH						
			AT THEN; DEWA IS ENTITLEDTO A REDUCTION IN						
			THE PO VALUE BY 1.25% PER WEEK OF DELAY AND						
			SUBJECT TOMAXIMUM 10% OF PO						
			VALUE.RETENTION A						
			MOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL						
			BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR						
			AFTER THE COMPLETION CERTIFICATE IS						
			ISSUED.IT WI						





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			LL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
10		ITEM-00010	RECTIFY AHU3-3 BLOWERBEARING DEFECT@GRDNSUBSTATION NAME - GRDN 400KVSAP - 30346708AIR HANDLING UNIT AHX 3-3MAKE # CARRIER; MODEL - 3 GAFLH43ELA91A-7; SL # SMAH08122611AHU-3-3 BLOWER BEARING & SHAFT IS DEFECTIVE, SHALL BE REPLACED, TESTEDAND COMMISSIONEDAND REINSTAT E THE UNIT BACK TO NORMAL WORKING CONDITION.CONTACT PERSON FOR SITE VISIT: RASHID KALLERY # SR ENGR MOB: 052-5507585WARRANTY - 1 YEA R FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 12 MONTHS OF PORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED, IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
11		ITEM-00011	REPLACE NRD IN PAC UNIT PU2-1 @ NDHMRSTHSAP - 30347781PACKAGE AC UNIT PU 2-1ZAMIL COOLINE; MODEL NUMBER - PRL025LDCCDMNVAMGEAASERIAL NUMBER - LOHBB0002MPACKAGE UNIT NRD-NO RETURN DAMPER IS DEFECTIVE NOT FUNCTIONING, SHALL BEREPLACED WITH NEW NRD.MR. ASIF (MOB- 050 6705246)PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 1 YEAR OF PORELEASE DATE, IF THE WORK I S DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF P	1	EA				





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			O VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFIC ATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIA LS SUPPLIED.						

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.





RFQ NUMBER : 2332400939

DATE : 16.04.2024 **REQ No** : 1032401319

REQ TITLE : Rectify 1032401415

DELIVERY LOCATION

CLOSING DATE : 30.04.2024

CLOSING TIME : 10:00:00

5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP