

**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS	5.000	М				
			IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP						
			ORDER NO: 521277016SCOPE OF WORK: #VISIT THE						
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS#REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE#REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE:#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY.#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY-#REPLACEMENT OF PC2RK						
			SOUNDER - 15 QTY.#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY.#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						
			SURVEY WILL BECONDUCTED ONLY ONE DAY						
			ONCE RFX IS RELEASED.ALL INTERESTED						
			VENDORS TO CONT						
			ACT ENGR. NARAYANSAMY						
			04-32293338,058-8908575 IMMEDIATELY TO ATTEND						
			SITE SURVEY. VARIATION WILL NOT BE ACCEPTED						
			IN EXECUTION STAGES.W						
			ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK						
			TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE						
			OF PO UNLESS DELAYED BYDEWA OUTAGES.						
2		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS	15	EA				
			IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP						
			ORDER NO: 521277016SCOPE OF WORK: #VISIT THE						
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS.:#REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE. #REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE:#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY-#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY.#REPLACEMENT OF PC2RK						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SOUNDER - 15 QTY-#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY-#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED  MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						
			SURVEY WILL BECONDUCTED ONLY ONE DAY						
			ONCE RFX IS RELEASED.ALL INTERESTED						
			VENDORS TO CONT						
			ACT ENGR. NARAYANSAMY						
			04-32293338,058-8908575 IMMEDIATELY TO ATTEND SITE SURVEY.VARIATION WILL NOT BE ACCEPTED						
			IN EXECUTION STAGES.W						
			ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK						
			TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE						
			OF PO UNLESS DELAYED BYDEWA OUTAGES.						
-			CITO CITELOG BELLTIED BIBLIOT CONTICLO.						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP						
			ORDER NO: 521277016SCOPE OF WORK: #VISIT THE						
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS. #REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE.·#REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE.#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY-#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY.#REPLACEMENT OF PC2RK						
			SOUNDER - 15 QTY·#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY-#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SURVEY WILL BECONDUCTED ONLY ONE DAY ONCE RFX IS RELEASED.ALL INTERESTED VENDORS TO CONT ACT ENGR. NARAYANSAMY 04-32293338,058-8908575 IMMEDIATELY TO ATTEND SITE SURVEY.VARIATION WILL NOT BE ACCEPTED IN EXECUTION STAGES.W ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE OF PO UNLESS DELAYED BYDEWA OUTAGES.						
4		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP ORDER NO: 521277016SCOPE OF WORK: #VISIT THE S ITE AND ASSESS THE REQUIREMENTS. #REPLACEMENT OF FIRE ALARM CABLE - 6000 METER APPROXIMATE. #REPLACEMENT OF LHS CABLE - 5000 METER A PPROXIMATE #REPLACEMENT OF MCP WCP1A MODEL - 15 QTY #REPLACEMENT OF FMM-101 MODULE - 15 QTY #REPLACEMENT OF PC2RK SOUNDER - 15 QTY #		EA				



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY.#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						
			SURVEY WILL BECONDUCTED ONLY ONE DAY						
			ONCE RFX IS RELEASED.ALL INTERESTED						
			VENDORS TO CONT						
			ACT ENGR. NARAYANSAMY						
			04-32293338,058-8908575 IMMEDIATELY TO ATTEND						
			SITE SURVEY.VARIATION WILL NOT BE ACCEPTED						
			IN EXECUTION STAGES.W						
			ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE						
			OF PO UNLESS DELAYED BYDEWA OUTAGES.						
		ITEM 00004							
5		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP	2	EA				



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ORDER NO: 521277016SCOPE OF WORK: #VISIT THE						
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS#REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE.:#REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE.#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY-#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY-#REPLACEMENT OF PC2RK						
			SOUNDER - 15 QTY.#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY-#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						
			SURVEY WILL BECONDUCTED ONLY ONE DAY						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ONCE RFX IS RELEASED.ALL INTERESTED						
			VENDORS TO CONT						
			ACT ENGR. NARAYANSAMY						
			04-32293338,058-8908575 IMMEDIATELY TO ATTEND						
			SITE SURVEY. VARIATION WILL NOT BE ACCEPTED						
			IN EXECUTION STAGES.W						
			ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK						
			TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE						
			OF PO UNLESS DELAYED BYDEWA OUTAGES.						
6		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS	2	EA				
			IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP						
			ORDER NO: 521277016SCOPE OF WORK: #VISIT THE						
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS.:#REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE#REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE.#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY-#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY.#REPLACEMENT OF PC2RK						
			SOUNDER - 15 QTY.#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			QTY-#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED		1				



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			DURINGCONFINED SPACE WORKING .APPROVED CABLES - PRYSMIAN UK FP PLUS, CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME X-950.APPROVED LHS CABLE - PROTECTOWIRE PLR-190 R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE AD88P-0500ALL DEWA PTW PROCEDURES, DEWA OUTAGE REQUIREMENTS, WORKING HOURS ANDSCHEDULE TO B E FOLLOWED DURING ENTIRE TIME OF WORK. SITE SURVEY WILL BECONDUCTED ONLY ONE DAY ONCE RFX IS RELEASED.ALL INTERESTED VENDORS TO CONT ACT ENGR. NARAYANSAMY 04-32293338,058-8908575 IMMEDIATELY TO ATTEND SITE SURVEY.VARIATION WILL NOT BE ACCEPTED IN EXECUTION STAGES.W ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE OF PO UNLESS DELAYED BYDEWA OUTAGES.						
7		ITEM-00001	RECTIFICATION OF FIRE ALARM SYSTEM DEFECTS IN AT MUSH-MBCH 400KV TUNNELTECH BLDG-4SAP ORDER NO: 521277016SCOPE OF WORK::#VISIT THE	6.000	М				



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			S						
			ITE AND ASSESS THE						
			REQUIREMENTS#REPLACEMENT OF FIRE ALARM						
			CABLE - 6000 METER						
			APPROXIMATE.:#REPLACEMENT OF LHS CABLE -						
			5000 METER A						
			PPROXIMATE:#REPLACEMENT OF MCP WCP1A						
			MODEL - 15 QTY.#REPLACEMENT OF FMM-101						
			MODULE - 15 QTY-#REPLACEMENT OF PC2RK						
			SOUNDER - 15 QTY.#						
			REPLACEMENT OF 5451 HEAT DETECTOR # 2						
			QTY.#REPLACEMENT OF 2151 SMOKE DETECTOR-2						
			QTYMAKE OF FACP: NOTIFIER UK, NFS2-3030						
			SERIESACTUAL						
			QUANTITY TO BE VERIFIED AT SITETHE SCOPE OF						
			WORK INCLUDES SUPPLY OF MATERIALS,						
			REMOVAL OF OLD DEVICESAND CABLES,						
			INSTALLATION AND S						
			UCCESSFUL TESTING AS PER						
			DEWA-TPCOMMISSIONING						
			PROCEDURES.REPLACED CABLES AND DEVICES						
			TO BE SUCCESSFULLY TESTED AS PER						
			DEWA-TPSCOMMIS						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SIONING PROTOCOL.ONLY VENDORS WITH						
			PREVIOUS EXPERIENCE FOR FIRE ALARM CABLING						
			WORKS INTRANSMISSION SUBSTATIONS ONLY						
			WILL BE CONSIDER						
			ED FOR THE JOB.DISPOSAL OF REMOVED						
			MATERIALS SHALL BE CONSIDERED UNDER						
			SCOPE.DEDICATED HSE ENGINEER FROM						
			CONTRACTOR TO BE PRESENT DU						
			RING WORK INCONFINED SPACES LIKE						
			TUNNEL.CONTRACTOR MUST ENSURE ALL SAFETY						
			MEASURES AND DEVICES REQUIRED						
			DURINGCONFINED SPACE WORKING						
			.APPROVED CABLES - PRYSMIAN UK FP PLUS,						
			CAVICEL ITALY SR114E, TF KABLEPOLAND FLAME						
			X-950.APPROVED LHS CABLE - PROTECTOWIRE						
			PLR-190						
			R, SAFE FIRE TC190-P, PROLINEPH88, KIDDE						
			AD88P-0500ALL DEWA PTW PROCEDURES, DEWA						
			OUTAGE REQUIREMENTS, WORKING HOURS						
			ANDSCHEDULE TO B						
			E FOLLOWED DURING ENTIRE TIME OF WORK. SITE						
			SURVEY WILL BECONDUCTED ONLY ONE DAY						
			ONCE RFX IS RELEASED.ALL INTERESTED						



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			VENDORS TO CONT						
			ACT ENGR. NARAYANSAMY						
			04-32293338,058-8908575 IMMEDIATELY TO ATTEND						
			SITE SURVEY. VARIATION WILL NOT BE ACCEPTED						
			IN EXECUTION STAGES.W						
			ARRANTY TO BE PROVIDED FOR 24 MONTHSWORK						
			TO BE COMPLETED WITHIN 8 WEEKS FROM ISSUE						
			OF PO UNLESS DELAYED BYDEWA OUTAGES.						

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

#### **SPECIAL NOTES / INSTRUCTIONS:**

Rectification of Fire alarm system @TB4

#### **STANDARD TERMS & CONDITIONS**

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.



**RFQ NUMBER** : 2332402185

**DATE** : 30.08.2024

**REQ No** : 1032403039

**REQ TITLE** : Rectification of Fire alarm s

**DELIVERY LOCATION** 

**CLOSING DATE** : 05.09.2024

CLOSING TIME : 10:00:00

5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP