

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332502300

DATE : 15.09.2025

REQ No : 1032504281

REQ TITLE : Rectification of DLP

DELIVERY LOCATION

CLOSING DATE : 18.09.2025

CLOSING TIME : 10:00:00

| SL NO | ITEM CODE | SERVICE ID | DESCRIPTION | QTY | UOM | BRAND/ORIGIN | WARRANTY | UNIT PRICE | TOTAL PRICE |
|-------|-----------|------------|--|-----|-----|--------------|----------|------------|-------------|
| 1 | | ITEM-00001 | SUBSTATION:DGASRECTIFICATION OF DIESEL PUMP CONTROLLER AS IT IS FOUND THAT THE RIBBINCABLES FROM CONTROLLER POWER SUPPLY TO CHARGER FOUND BURNT FOR CHARGER-2AND PSU TRANSFORMER ALSO FOUND DAMAGED DUE TO OVER CURRENTCONTROLLER START-UP DATE:MAY/2007CONTROLLER MANUF ACTURER NAME: TORNATECHCONTROLLER MODEL NO: GPD-N-24-F-BCE-10·SUPPLY OF ALL NECESSARY SPARES REQUIRED FOR RECTIFICATION·SIX MONTHS W ARRANTY FOR WORKMANSHIP AND REPLACED COMPONENTSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO·CALL SHERIEF (529219010), USMAN (561721269) FOR ANY INQUIRY | 1 | EA | | | | |
| 2 | | ITEM-00002 | SUBSTATION:LSTC. RECTIFICATION OF DIESEL PUMP CONTROLLER AS IT IS FOUND THAT CRANK-1&2IS NOT WORKING IN MANUAL MODE FROM DLP CONTROL LER BUT IT IS WORKING FROMENGINE MOUNTED PANEL CRANKING SWITCHES·CONTROLLER | 1 | EA | | | | |

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332502300

DATE : 15.09.2025

REQ No : 1032504281

REQ TITLE : Rectification of DLP

DELIVERY LOCATION

CLOSING DATE : 18.09.2025

CLOSING TIME : 10:00:00

| SL NO | ITEM CODE | SERVICE ID | DESCRIPTION | QTY | UOM | BRAND/ORIGIN | WARRANTY | UNIT PRICE | TOTAL PRICE |
|-------|-----------|------------|--|-----|-----|--------------|----------|------------|-------------|
| | | | START-UP DATE:APRIL/ 2011CONTROLLER MANUFACTURER NAME: T ORNATECHCONTROLLER MODEL NO: GPD-N-24-F-BCE-10.SUPPLY OF ALL NECESSARY SPARES REQUIRED FOR RECTIFICATION.SIX MONTHS WARRANTY FOR WOR KMANSHIP AND REPLACED COMPONENTS WORK TO BECOMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO.CALL SHERIEF (529219010), USMAN (561721269) FOR ANY INQUIRY | | | | | | |
| 3 | | ITEM-00003 | SUBSTATION:LAKE. RECTIFICATION OF DIESEL PUMP CONTROLLER AS IT IS FOUND THAT THECONTROLLER BOARD IS NOT WORKING AND DISPLAY IS IN OF F CONDITION.CONTROLLER START-UP DATE:NOV/ 2005CONTROLLER MANUFACTURER NAME: TORNATECHCONTROLLER MODEL NO: GPD-N-12F-BCE-10.SUPPLY OF ALL NECESSARY SPARES REQUIRED FOR RECTIFICATION.SIX MONTHS WARRANTY FOR WORKMANSHIP AND REPLACED COMPONENTS WORK TO BECOMPLETED WIT | 1 | EA | | | | |

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332502300
DATE : 15.09.2025
REQ No : 1032504281
REQ TITLE : Rectification of DLP
DELIVERY LOCATION
CLOSING DATE : 18.09.2025
CLOSING TIME : 10:00:00

| SL NO | ITEM CODE | SERVICE ID | DESCRIPTION | QTY | UOM | BRAND/ORIGIN | WARRANTY | UNIT PRICE | TOTAL PRICE |
|-------|-----------|------------|--|-----|-----|--------------|----------|------------|-------------|
| | | | HIN 2 WEEKS FROM ISSUE OF PO.CALL SHERIEF (529219010), USMAN (561721269) FOR ANY INQUIRY | | | | | | |

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Rectification of DLP controller

STANDARD TERMS & CONDITIONS

- Prices should be 'DDP' delivery duty paid at DEWA stores.
- Quotation to be submitted only in local currency U.A.E Dirhams
- DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332502300

DATE : 15.09.2025

REQ No : 1032504281

REQ TITLE : Rectification of DLP

DELIVERY LOCATION

CLOSING DATE : 18.09.2025

CLOSING TIME : 10:00:00

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP