



RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
1		ITEM-00001	REPLACE CHW VALVES AND GAUGES @ YBRIBRIEF	1	EA				
			SCOPE OF WORKS:SUBSTATION NAME - YBRI						
			132KVDEFECTIVE 3-PORT MOTORISED VALVE OF						
			DIA 100 MM						
			TO BE REPLACED WITHAPPROVED MAKE (
			SIEMENS) FOR AHU-1 & AHU-1A .2 NOS						
			UNITS.MOTORISED BUTTERFLY VALVE FOR AHU-1,						
			1A(100 MM DIA) & A						
			HU-02(DIA 80MM) TO BE REPLACED BY THE						
			CONTRACTOR.4 NOS PRESSURE GAUGE FOR						
			AHU-1 & AHU-1A 1/2 INCH SIZE MATERIAL:						
			CARBONSTEEL OR COP						
			PER. SHALL BE SUPPLIED AND INSTALLED BY THE						
			CONTRACTOR ANDREINSTATE THE						
			SYSTEM.CONTACT PERSON FOR SITE VISIT - MR						
			RASHID KALLERY : (
			PH: 04-32-21477 #MOB: 0525507585)PAYMENT						
			TERMS AND CONDITIONS:PENALTY: THE						
			CONTRACTOR SHALL COMPLETE THIS WORK						
			WITHIN 1 YEAR OF PORE						
			LEASE DATE, IF THE WORK IS DELAYED BEYOND						
			THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN						
			THE PO VALUE BY 1.25% PER WEEK OF DELAY AND						





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			S UBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTE R THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
2		ITEM-00002	DAMPER WITH ACTUATOR AND CAMLOCKS @ YBRIBRIEF SCOPE:SUBSTATION NAME - YBRI 132KVRETURN AIR DAMPER FOR AHU-1A TO BE REPLACED WITH ACT UATOR; SIZE: 600X600 MM.16 NOS CAM LOCKS TO BE REPLACED FOR ALL DUCTS ACCESS DOOR.REINSTATE THE SYSTEM BACK TO NORMAL WORKING CONDI TION.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.CONTACT PERSON FOR SITE VISIT - MR RASHID KALLERY: (PH: 04-32-214 77 #MOB: 0525507585)	1	EA				
3		ITEM-00003	REPLACE DUCTED INLINE FAN BEF-4 @ YBRISAP- 30351852SUBSTATION NAME - YBRI	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
			132KVBASEMENT EXTRACT FAN BEF 4 (DUCTED INLINE FAN)MAKE - SYSTEMAIR; MODEL - KVK 160MDEFECTIVE IN-LINE DUCTED EXHAUST FAN TO BE REMOVED. NEW EXHAUST FAN OFTHE SAME CAPACITY SHALL BE FIXED INSTALLED AND TESTED AS PER THE DEWASTANDARDS.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.CONTACT PERSON FOR SITE V ISIT - MR RASHID KALLERY: (PH: 04-32-21477 #MOB: 0525507585)						
4		ITEM-00004	REPLACE DUCTED INLINE FAN BEF-3 @ YBRISAP-30351851SUBSTATION NAME - YBRI 132KVBASEMENT EXTRACT FAN BEF 3 (DUCTED INLINE FAN)MAKE - SYSTEMAIR; MODEL - KVK 160MDEFECTIVE IN-LINE DUCTED EXHAUST FAN TO BE REMOVED. NEW EXHAUST FAN OFTHE SAME CAPACITY SHALL BE FIXED INSTALLED AND TESTED AS PER THE DEWASTANDARDS.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SUPPLIED.CONTACT PERSON FOR SITE V ISIT - MR RASHID KALLERY : (PH: 04-32-21477 #MOB: 0525507585)						
5		ITEM-00005	REPLACE DUCTED INLINE FAN BEF-2 @ YBRISAP-30351850SUBSTATION NAME - YBRI 132KVBASEMENT EXTRACT FAN BEF 2 (DUCTED INLINE FAN)MAKE - SYSTEMAIR; MODEL - KVK 160MDEFECTIVE IN-LINE DUCTED EXHAUST FAN TO BE REMOVED. NEW EXHAUST FAN OFTHE SAME CAPACITY SHALL BE FIXED INSTALLED AND TESTED AS PER THE DEWASTANDARDS.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.CONTACT PERSON FOR SITE V ISIT - MR RASHID KALLERY: (PH: 04-32-21477 #MOB: 0525507585)	1	EA				
6		ITEM-00006	REPLACE DUCTED INLINE FAN BEF-1 @ YBRISAP-30351849SUBSTATION NAME - YBRI 132KVBASEMENT EXTRACT FAN BEF 1 (DUCTED INLINE FAN)MAKE - SYSTEMAIR; MODEL - KVK 160MDEFECTIVE IN-LINE DUCTED EXHAUST FAN TO BE REMOVED. NEW	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			EXHAUST FAN OFTHE SAME CAPACITY SHALL BE FIXED I NSTALLED AND TESTED AS PER THE DEWASTANDARDS.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.CONTACT PERSON FOR SITE VI SIT - MR RASHID KALLERY: (PH: 04-32-21477 #MOB: 0525507585)						
7		ITEM-00007	INSTALL PHASE DISCONNECTORS IN AHUS@YBRISUBSTATION NAME - YBRI 132KVAIR HANDLING UNIT AHW 1-A , AHU 1, AHU2 & AHU2A (CW TYPE)MAKE - CARRIERMODEL - 39G;ISOLATOR FOR AHU-1A DEFECTIVE. TO BE REPLACED BY THE CONTRACTOR ANDPHASE DISCONNECTOR FOR AHU-1, AHU-1A , AHU-2 & AHU-2A IS DEFECTIVE(4NOS) TO BE SUPPLIED & INSTALLED BY THE CONTRACTOR.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIE D.CONTACT PERSON FOR SITE VISIT - MR RASHID KALLERY: (PH: 04-32-21477 #MOB: 0525507585)	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
			YBRISUBSTATION NAME - YBRI 132KVSAP -						
			30346371CHILLER - 1MAKE - CARRIERMODEL -						
			30GTN060-F9						
			33SL # R 3304F 52110CHILLER -02 REFRIGERANT						
			LINE ENTERING EVAPORATOR SIDE IS LEAKING.						
			THELEAKAGE TO BE RECTIFIED BY PROPER						
			WELDING O						
			F COPPER PIPE WITH MS BYUSING TRANSITION						
			COUPLER. UNIT TO BE PRESSURE TESTED AND						
			RECOMMISSIONEDAFTER RECTIFYING THE						
			LEAKAGE. CONTRAC						
			TOR SHALL RECTIFY ASSOCIATED ANDREINSTATE						
			THE UNIT BACK TO NORMAL WORKING						
			CONDITION.WARRANTY - 1 YEAR FOR						
			WORKMANSHIP AND NEW MATERI						
			ALS SUPPLIED.CONTACT PERSON FOR SITE VISIT -						
			MR RASHID KALLERY : (PH: 04-32-21477 #MOB:						
			0525507585)PAYMENT TERMS AND						
			CONDITIONS:PENA						
			LTY: THE CONTRACTOR SHALL COMPLETE THIS						
			WORK WITHIN 1 YEAR OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENTIT						





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			LEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED, IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
9		ITEM-00009	AHU-4C BLOWER MOTOR ASSEMBLY DEFECTS@WRSNUNIT DETAILS:SAP - 30346649AIR COOLED CONDENSING UNIT ACCU 4-CMAKE - CARRIERMODEL - 38AH-06 4-C923SL NUMBER - 1007Q08130SUBSTATION NAME - WRSN 400KVACCU UNIT BLOWER ASSEMBLY DEFECTS SHALL BE RECTIFIED OR REPLACE BY THECONTRA CTOR.ASSOCIATED DEFECTS SHALL BE RECTIFIED BY THE CONTRACTOR.CONTACT DETAILS FOR SITE VISIT:MR RASHID NAQBI - MOBILE: 04-32 21090 / 052- 7778821RASHID.ALNAQBI@DEWA.GOV.AEWARRAN		EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.PAYMENT TERMS AND CONDITIONS:PENAL TY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 1 YEAR OF PORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITL EDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED, IT WILL BE RELEASED TO THE C						
10		ITEM-00010	ONTRACTOR UPON CLEARING ALL RELATED NODS. REPLACE BUTTERFLY VALVE & ACTUATOR @LULUSUBSTATION NAME - LULU 132KVAHU 1A BUTTERFLY VALVE ACTUATOR IS DEFECTIVE, TO BE REPLACED BY THECONTRACTORACTUATOR - 1 NO.MAKE - TYCOMODEL - TVC-ER60**AHU-1 BUTTER FLY DIA - 100 MM WITH ACTUATOR - PN-16 .SUPPLY	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			,INSTALLATION & TESTING SHALL BE DONE BY THE CONTRACTOR. MAKE: SIEMENSCONTACT DETAILS FOR SITE VISIT:WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MAT ERIALS SUPPLIED.CONTACT PERSON FOR SITE VISIT- MR RASHID KALLERY: (PH: 04-32-21477 #MOB: 0525507585)						
11		ITEM-00011	CHILLER-02 RECTIFICATION WORKS @ KHLSSUBSTATION NAME - KHLS 132KVSAP - 30346359CHILLER - 1MAKE - YORKMODEL - YCAL0217EC50XCASXTXHSL # RHRM015906SCOPE OF WORKS: 1. REMOVE THE OLD CHILLER UNIT FOUNDATION. 2. MAKE NEWCHILLER FOUNDATION WITH 3-LAYER STEEL 14MM WITH SO LID CONCRETE. 3. CURETHE NEW FOUNDATION TO MAINTAIN SATISFACTORY TEMPERATURE & MOISTURECONDITIONS IN CONCRETE LONG ENOUGH FOR HYDRAT ION TO DEVELOP THE DESIREDCONCRETE PROPERTIES. 4. SUPPLY & INSTALLATION OF	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			INSTALLATION OF 4#						
			FLEXIBLE PIPE CONNECTOR # 1 NO. 6.SUPPLY &						
			INSTALLATION OF 4# CRANE BUTTERFLY VALVE # 1						
			NO. 7. SUPPLY &INSTALLATION OF WATER FLOW S						
			WITCH # 1 NO. 8. REPAIRING OF THE						
			DAMAGEDCLADDING FROM BUTTERFLY VALVE TO						
			CHILLER COOLER. 9. TEST & COMMISSIONTHE						
			UNIT. 10. EVAPORAT						
			OR TO BE PAINTED WITH EPOXY AND TO BE						
			INSULATEDWITH WEATHER COATING AND						
			CANVASS CLOTH.WARRANTY - 1 YEAR FOR						
			WORKMANSHIP AND NEW MATE						
			RIALS SUPPLIED.CONTACT PERSON FOR SITE VISIT						
			- MR RASHID KALLERY : (PH: 04-32-21477 #MOB:						
			0525507585)PAYMENT TERMS AND CONDITIONS:PE						
			NALTY: THE CONTRACTOR SHALL COMPLETE THIS						
			WORK WITHIN 1 YEAR OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENT						
			ITLEDTO A REDUCTION IN THE PO VALUE BY 1.25%						
			PER WEEK OF DELAY AND SUBJECT TOMAXIMUM						
			10% OF PO VALUE.RETENTION AMOUNT: 5% OF						
			THE TOT						





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			AL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO TH E CONTRACTOR UPON CLEARING ALL RELATED NODS.						
12		ITEM-00012	CHILLER-01 RECTIFICATION WORKS @ KHLSSUBSTATION NAME - KHLS 132KVSAP - 30346358CHILLER - 1MAKE - YORKMODEL - YCAL0217EC50XCASXTXHSL # RHRM015905SCOPE OF WORKS: 1. REMOVE THE OLD CHILLER UNIT FOUNDATION. 2. MAKE NEWCHILLER FOUNDATION WITH 3-LAYER STEEL 14MM WITH SO LID CONCRETE. 3. CURETHE NEW FOUNDATION TO MAINTAIN SATISFACTORY TEMPERATURE & MOISTURECONDITIONS IN CONCRETE LONG ENOUGH FOR HYDRAT ION TO DEVELOP THE DESIREDCONCRETE PROPERTIES. 4. SUPPLY & INSTALLATION OF VIBRATION ISOLATOR # 4NOS. 5. SUPPLY & INSTALLATION OF 4# FLEXIBLE PIPE CONNECTOR # 1 NO. 6.SUPPLY &	1	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

L NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
			INSTALLATION OF 4# CRANE BUTTERFLY VALVE # 1						
			NO. 7. SUPPLY &INSTALLATION OF WATER FLOW S						
			WITCH # 1 NO. 8. REPAIRING OF THE						
			DAMAGEDCLADDING FROM BUTTERFLY VALVE TO						
			CHILLER COOLER. 9. TEST & COMMISSIONTHE						
			UNIT. 10. EVAPORAT						
			OR TO BE PAINTED WITH EPOXY AND TO BE						
			INSULATEDWITH WEATHER COATING AND						
			CANVASS CLOTH.WARRANTY - 1 YEAR FOR						
			WORKMANSHIP AND NEW MATE						
			RIALS SUPPLIED.CONTACT PERSON FOR SITE VISIT						
			- MR RASHID KALLERY : (PH: 04-32-21477 #MOB:						
			0525507585)PAYMENT TERMS AND CONDITIONS:PE						
			NALTY: THE CONTRACTOR SHALL COMPLETE THIS						
			WORK WITHIN 1 YEAR OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENT						
			ITLEDTO A REDUCTION IN THE PO VALUE BY 1.25%						
			PER WEEK OF DELAY AND SUBJECT TOMAXIMUM						
			10% OF PO VALUE.RETENTION AMOUNT: 5% OF						
			THE TOT						
			AL VALUE OF THE PO WILL BE KEPT AS						
			ARETENTION AMOUNT FOR 1 YEAR AFTER THE						





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO TH E CONTRACTOR UPON CLEARING ALL RELATED NODS.						
13		ITEM-00013	RECTIFY PU-1 BLOWER MOTOR BASE @ DSOSSAP - 30347183PACKAGE AC UNIT PU 1SUBSTATION NAME - DSOS 132KVPACKAGE UNIT PU-1 BLOWER MOTOR BA SE DEFECT, SHALL BE RECTIFIED ORREPLACE BY THE CONTRACTOR.ASSOCIATED DEFECTS SHALL BE RECTIFIED BY THE CONTRACTOR.CONTACT DETAILS FO R SITE VISIT:MR RASHID NAQBI - MOBILE: 04-32 21090 / 052-7778821RASHID.ALNAQBI@DEWA.GOV.AEWARRAN TY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.	1	EA				
14		ITEM-00014	REPLACEMENT OF 2NOS CHILLERS COOLER INSULATION AT KHLS 132KVLOCATION REF.: KHLS 132KW _NOD NO.: 420442241: YORK CHILLER NO. 1 _REPLA CEMENT OF COOLER INSULATION SCOPE OF	2	EA				





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WORKS: 1. REMOVAL OF THECOOLER INSULATION, APPLY EPOXY PAINT & INSULATE THE SAME WITH RUBBERSHE ET, CANVAS CLOTH & FOSTER.LOCATION REF.: KHLS 132KW _NOD NO.: 420442241: YORK CHILLER NO. 2 _REPLACEMENT OF COOLER INSULATION SCOPE OF WORKS: 1. REMOVAL OF THECOOLER INSULATION, APPLY EPOXY PAINT & INSULATE THE SAME WITH RUBBERSHEET, CANVAS CLOTH & FOSTER.WARRANTY - 1 YEAR FOR WORKMANSHIP AND NEW MATERIALS SUPPLIED.CONTACT PERSON - MR RASHID KALLERY: (PH: 04-32-21477 # MOB:						
			0525507585)						

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS





RFQ NUMBER : 2412400050

DATE : 15.01.2024 **REQ No** : 1032304757

REQ TITLE : Duct Replacement 1032304757

DELIVERY LOCATION

CLOSING DATE : 26.01.2024

CLOSING TIME : 10:00:00

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP