



RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
	ITEM-00001	OVERHAULING OF DN 250 PARCOL BUTTERFLY	1	EA				
		VALVE AT K STN PHASE 2 BLENDING PLANT.						
		SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL						
		THE VALVE						
		WITH REPLACEMENT OF DAMAGED PARTS						
		INCLUDING FASTENERS, TRANSPORTATION IF ANY,						
		MATERIAL HANDLING, BLASTING AND PAINTING,						
		ASSEMBLY OF						
		VALVE, TESTING AND INSTALLATION. COMPLETE						
		WORKS ASSOCIATED WITH THE JOB IS IN						
		CONTRACTOR'S SCOPE. JOB COMPLETION SHALL						
		BE ONLY AFTER						
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						
		1 ` '						
		1 ' '						
		` '						
		· ·						
	ITEM CODE		ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/ SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST REMOVAL OF ALL PARTS AFTER DISMANTLING.	ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/ SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST	ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/ SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST REMOVAL OF ALL PARTS AFTER DISMANTLING.	ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/BUSH/BEARING/SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST REMOVAL OF ALL PARTS AFTER DISMANTLING.	ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/ SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST REMOVAL OF ALL PARTS AFTER DISMANTLING.	ITEM-00001 OVERHAULING OF DN 250 PARCOL BUTTERFLY VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WITH REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VALVE, TESTING AND INSTALLATION. COMPLETE WORKS ASSOCIATED WITH THE JOB IS IN CONTRACTOR'S SCOPE. JOB COMPLETION SHALL BE ONLY AFTER SUCCESSFUL TESTING OF VALVE. DISMANTLING: (1) REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2) REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3) DISMANTLING THE COMPLETE VALVE. (4) INSPECTION OF VALVE INDIVIDUAL PARTS AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/ SHAFT FOR BUTT ERFLY/BEARING/SEAT RING (5) CLEANING & RUST REMOVAL OF ALL PARTS AFTER DISMANTLING.





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE: PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			REPLAC						
			EMENT OF DAMAGED/DEFORMED/CORRODED						
			SPARE PARTS. (2) REPLACEMENT OF CORRODED						
			STUDS & BOLTS WHEREVER NECESSARY. (3)						
			SERVICING OF ACT						
			UATOR ASSEMBLY. (4) ASSEMBLING BACK THE						
			VALVE. (5) VALVE BODY CLEANING AND PAINTING.						
			(6) MOUNTING OF ACTUATOR ASSEMBLY. (7) CARR						
			Y OUT THE TESTING OF THE VALVE # AS PER API						
			598 (8) INSTALL VALVE BACK TO SYSTEM WITH						
			NEW GASKETS. WARRANTY - 1 YEAR						
			COMPLETION T						
			IME: 8 DAYS CONTRACTOR SCOPE: ALL SPARES						
			THE CONTRACTOR SHALL ENSURE HANDLING OF						
			VALVES CAREFULLY TO AVOID ANY DAMAGE TO						
			THE FLANG						
			ES OF VALVES DURING MAINTENANCE. CRANE,						
			FORK-LIFT AND SCAFFOLDING IF REQUIRED, WILL						
			BE ARRANGED BY DEWA. MANPOWER,						
			CONSUMABLES, FAST						
			ENERS, GASKETS, TOOLS AND TACKLES						
			REQUIRED FOR THE JOB SHALL BE ARRANGED BY						
			THE CONTRACTOR. SAFETY OF PERSONNEL			1			





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WORKING AGAINST THIS						
			JOB IS THE RESPONSIBILITY OF CONTRACTOR.						
			THEY SHALL STRICTLY ADHERE WITH DEWA						
			SAFETY, ENVIRONMENT AND CONTRACT LABOUR						
			REGULATIONS						
			FOR MORE DETAILS AND SITE VISIT, PLEASE						
			CONTACT: MR. JAMES KUMAR MOBILE - 0529126512						
			EMAIL # JAMES.KUMAR@DEWA.GOV.AE						
2	2	ITEM-00002	OVERHAULING OF DN400 ITALVALV BUTTERFLY	1	EA				
			VALVE AT K STN PHASE 2 BLENDING PLANT.						
			SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL						
			THE VALVE						
			WITH REPLACEMENT OF DAMAGED PARTS						
			INCLUDING FASTENERS, TRANSPORTATION IF ANY,						
			MATERIAL HANDLING, BLASTING AND PAINTING,						
			ASSEMBLY OF						
			VALVE, TESTING AND INSTALLATION. COMPLETE						
			WORKS ASSOCIATED WITH THE JOB IS IN						
			CONTRACTOR'S SCOPE. JOB COMPLETION SHALL						
			BE ONLY AFTE						
			R SUCCESSFUL TESTING OF VALVE.						
			DISMANTLING: (1) REMOVAL OF VALVE ASSEMBLY						
			FROM SYSTEM. (2) DISMANTLING THE COMPLETE						





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			VALVE AND GEARB						
			OX. (3) INSPECTION OF VALVE INDIVIDUAL PARTS						
			AFTER THE REMOVAL, LIKE DISC/ BUSH/ BEARING/						
			SHAFT FOR BUTTERFLY/BEARING/SEAT RING (4)						
			CLEANING & RUST REMOVAL OF ALL PARTS AFTER						
			DISMANTLING. REPAIR, RECONDITIONING &						
			ASSEMBLY: (1) REPLACEMENT OF DAMAGED/						
			DEFORMED/						
			CORRODED SPARE PARTS. (2) REPLACEMENT OF						
			CORRODED STUDS & BOLTS WHEREVER						
			NECESSARY. (3) SERVICING OF GEARBOX. (4)						
			ASSEMBLING BACK						
			THE VALVE. (5) VALVE BODY CLEANING AND						
			PAINTING. (6) MOUNTING OF GEARBOX ASSEMBLY.						
			(7) CARRY OUT THE TESTING OF THE VALVE # AS P						
			ER API 598 (8) INSTALL VALVE BACK TO SYSTEM						
			WITH NEW GASKETS. WARRANTY - 1 YEAR						
			COMPLETION TIME: 8 DAYS CONTRACTOR SCOPE:						
			ALL SP						
			ARES THE CONTRACTOR SHALL ENSURE						
			HANDLING OF VALVES CAREFULLY TO AVOID ANY						
			DAMAGE TO THE FLANGES OF VALVES DURING						
			MAINTENANCE. CRAN		1				





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			E, FORK-LIFT AND SCAFFOLDING IF REQUIRED, WILL BE ARRANGED BY DEWA. MANPOWER, CONSUMABLES, FASTENERS, GASKETS, TOOLS AND TACKLES REQ UIRED FOR THE JOB SHALL BE ARRANGED BY THE CONTRACTOR. SAFETY OF PERSONNEL WORKING AGAINST THIS JOB IS THE RESPONSIBILITY OF CONTRAC TOR. THEY SHALL STRICTLY ADHERE WITH DEWA SAFETY, ENVIRONMENT AND CONTRACT LABOUR REGULATIONS FOR MORE DETAILS AND SITE VISIT, PLEA SE CONTACT: MR. JAMES KUMAR MOBILE - 0529126512 EMAIL # JAMES.KUMAR @DEWA.GOV.AE						
3		ITEM-00003	OVERHAULING OF DN 50 PARCOL CONTROL VALVE AT K STN PHASE 2 BLENDING PLANT. SCOPE OF WORK UNDER THIS PR IS TO OVERHAUL THE VALVE WIT H REPLACEMENT OF DAMAGED PARTS INCLUDING FASTENERS, TRANSPORTATION IF ANY, MATERIAL HANDLING, BLASTING AND PAINTING, ASSEMBLY OF VAL VE, TESTING AND INSTALLATION. COMPLETE	1	EA				





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAI PRICE
			WORKS ASSOCIATED WITH THE JOB IS IN						
			CONTRACTOR'S SCOPE. JOB COMPLETION SHALL						
			BE ONLY AFTER SU						
			CCESSFUL TESTING OF VALVE. DISMANTLING: (1)						
			REMOVAL OF PARCOL ACTUATOR ASSEMBLY. (2)						
			REMOVAL OF VALVE ASSEMBLY FROM SYSTEM. (3)						
			DIS						
			MANTLING THE COMPLETE VALVE. (4) INSPECTION						
			OF VALVE INDIVIDUAL PARTS AFTER THE						
			REMOVAL, LIKE SEAT/PLUG/STEM. (5) CLEANING &						
			RUST RE						
			MOVAL OF ALL PARTS AFTER DISMANTLING.						
			REPAIR, RECONDITIONING & ASSEMBLY: (1)						
			REPLACEMENT OF						
			DAMAGED/DEFORMED/CORRODED SPARE PARTS						
			. (2) REPLACEMENT OF CORRODED STUDS &						
			BOLTS WHEREVER NECESSARY. (3) SERVICING OF						
			ACTUATOR ASSEMBLY. (4) ASSEMBLING BACK THE						
			VALVE						
			. (5) VALVE AND ACTUATOR CLEANING AND						
			PAINTING. (6) MOUNTING OF ACTUATOR						
			ASSEMBLY. (7) CARRY OUT THE TESTING OF THE						
			VALVE # AS PE						





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE: PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			R API 598 (8) INSTALL VALVE BACK TO SYSTEM						TRIOL
			WITH NEW GASKETS. WARRANTY - 1 YEAR						
			COMPLETION TIME: 8 DAYS CONTRACTOR SCOPE:						
			ALL SPA						
			RES THE CONTRACTOR SHALL ENSURE HANDLING						
			OF VALVES CAREFULLY TO AVOID ANY DAMAGE TO						
			THE FLANGES OF VALVES DURING MAINTENANCE.						
			CRANE						
			, FORK-LIFT AND SCAFFOLDING IF REQUIRED, WILL						
			BE ARRANGED BY DEWA. MANPOWER,						
			CONSUMABLES, FASTENERS, GASKETS, TOOLS						
			AND TACKLES REQU						
			IRED FOR THE JOB SHALL BE ARRANGED BY THE						
			CONTRACTOR. SAFETY OF PERSONNEL WORKING						
			AGAINST THIS JOB IS THE RESPONSIBILITY OF						
			CONTRACT						
			OR. THEY SHALL STRICTLY ADHERE WITH DEWA						
			SAFETY, ENVIRONMENT AND CONTRACT LABOUR						
			REGULATIONS FOR MORE DETAILS AND SITE						
			VISIT, PLEAS						
			E CONTACT: MR. JAMES KUMAR MOBILE -						
			0529126512 EMAIL # JAMES.KUMAR@DEWA.GOV.AE						





RFQ NUMBER : 2332302115

DATE : 20.09.2023 **REQ No** : 1032303353

REQ TITLE : PARCOL CONTROL VALVES

DELIVERY LOCATION

CLOSING DATE : 26.09.2023

CLOSING TIME : 10:00:00

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

PARCOL CONTROL VALVES AND ITALVALV ISOLATION VALVE OVERHAULING WORKS; K2 BLENDING PLANT.

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP