

RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	OVERHAULING OF ELECTRO CHLORINATION	1	EA				
			TRANSFORMER C (TAG						
			NO.60GEN41GT001C)OVERHAULING OF 820KVA						
			TRANSFORMER AND RECTIFICATION OF OIL L						
			EAK, ANDGASKETS REPLACEMENT WORKS OF						
			ELECTRO CHLORINATION TRANSFORMER -, TAG						
			NO.60GEN41GT001C, MAKE: VTD TRASFORMATORI,						
			ITALY, 820KV						
			A 11/± 3X2,5% /157KV, SERIAL NO. 20705, MANF.						
			YEAR: 2004, AT ETS FACTORY.SCOPE OF WORK:1.						
			DE-ENERGIZE & DISCONNECT THE TRANSFORMER						
			F						
			ROM SERVICE BY DEWA.2. MOVE THE						
			TRANSFORMER FROM ITS POSITION AND BRING IT						
			OUTSIDE (TO BEDONE BY DEWA).3. LOAD THE						
			TRANSFORMER ON LO						
			W BED TRAILER (LOADING AT SITE TO						
			BEARRANGED BY DEWA). RECEIVE THE						
			TRANSFORMER AT VENDOR'S						
			FACTORY(UNLOADING AT FACTORY WILL BE AR						
			RANGED BY VENDOR). CONDUCT						
			VISUALINSPECTION & PRELIMINARY CHECKS.4.						
			CARRY OUT PRELIMINARY TESTING TO VERIFY						



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TRANSFORMER HEALTHINES						
			S.5. DRAIN THE OIL JUST BELOW THE BUSHING						
			LEVEL AND STORE IT SAFELY FORRE-USE.6.						
			REMOVE THE TOP COVER ACCESSORIES AND						
			DISMANTLE THE						
			TOP COVER.7. REPLACE THE LV BUSHINGS WITH						
			GASKET.8. REPLACE PRV GASKET.9. REPLACE THE						
			GASKETS OF RADIATORS, TOP COVER,						
			INSPECTION CO						
			VER, DRAINVALVE, ALL BUSHINGS, PRV ETC.						
			RE-TANK THE CORE AND COIL ASSEMBLY AND						
			FIXTHE TOP COVER WITH ALL THE						
			ACCESSORIES.10. RE-FILL						
			THE SAME OIL. VENDOR HAS TO INFORM DEWA IF						
			THEY NEED OIL,OIL WILL BE ARRANGED BY DEWA						
			IF EXTRA REQUIRED.11. CONDUCT PRESSURE						
			TEST B						
			Y APPLYING NITROGEN PRESSURE FOR 24 HOURS						
			TOCHECK OIL LEAKAGE.12. HOT OIL CIRCULATION						
			TO EXPEL MOISTURE AND IMPROVE BDV.13. TAKE						
			OIL						
			SAMPLE AND DO BDV & MOISTURE TEST AND						
			CONDUCT ROUTINE TESTSAS PER IEC 60076.						



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			GENERAL CLEANING.14. LOAD THE TRANSFORMER						
			ON ETS ARRA						
			NGED TRAILER (UNLOADING AT SITE TOBE						
			ARRANGED BY CUSTOMER).16. OIL FOR TOPPING						
			UP (IF REQUIRED) SHALL BE EXTRA. TAKING OUT						
			FROMFOUN						
			DATION AND RE-POSITIONING, LOADING AND						
			UNLOADING OF TRANSFORMER ATDEWA PS SHALL						
			BE ARRANGED BY DEWA.17. CABLE						
			DISCONNECTION, RE-CONN						
			ECTION & TERMINATION SHALL BE DONE						
			BYCUSTOMER (ALL CABLE WORK SHALL BE AT						
			YOUR END).18. CABLE GLANDS & CABLE LUGS,						
			INSULATION BOOTS						
			ARE NOT IN OUR SCOPE.19. NO CIVIL WORK IS						
			CONSIDERED.20. TRANSPORTATION OF						
			TRANSFORMER FROM CUSTOMER SITE TO						
			VENDORS FACTORYSHALL BE						
			DONE BY THE CONTRACTOR. CONTRACTOR HAS						
			TO ARRANGE INSURANCESTARTING FROM						
			COLLECTION OF TRANSFORMER FROM DEWA,						
			WHILE TRANSPORT (TOA						
			ND FRO), SERVICE AT VENDORS WORKSHOP TILL		1				



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RETURN BACK TO DEWA.21. ALL GATE PASSES / SECURITY PASSES SHALL BE ARRANGED BY DEWA.						
2		ITEM-00001	OVERHAULING OF ELECTRO CHLORINATION TRANSFORMER B (TAG NO.60GEN41GT001B)OVERHAULING OF 820KVA TRANSFORMER AND RECTIFICATION OF OIL L EAK, ANDGASKETS REPLACEMENT WORKS OF ELECTRO CHLORINATION TRANSFORMER -, TAG NO.60GEN41GT001B, MAKE: VTD TRASFORMATORI, ITALY, 820KV A 11/± 3X2,5% /157KV, SERIAL NO. 20704, MANF. YEAR: 2004, AT ETS FACTORY.SCOPE OF WORK:1. DE-ENERGIZE & DISCONNECT THE TRANSFORMER F ROM SERVICE BY DEWA.2. MOVE THE TRANSFORMER FROM ITS POSITION AND BRING IT OUTSIDE (TO BEDONE BY DEWA).3. LOAD THE TRANSFORMER ON LO W BED TRAILER (LOADING AT SITE TO BEARRANGED BY DEWA). RECEIVE THE TRANSFORMER AT VENDOR'S FACTORY (UNLOADING AT FACTORY WILL BE AR	1	EA				



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RANGED BY VENDOR). CONDUCT						
			VISUALINSPECTION & PRELIMINARY CHECKS.4.						
			CARRY OUT PRELIMINARY TESTING TO VERIFY						
			TRANSFORMER HEALTHINES						
			S.5. DRAIN THE OIL JUST BELOW THE BUSHING						
			LEVEL AND STORE IT SAFELY FORRE-USE.6.						
			REMOVE THE TOP COVER ACCESSORIES AND						
			DISMANTLE THE						
			TOP COVER.7. REPLACE THE LV BUSHINGS WITH						
			GASKET.8. REPLACE PRV GASKET.9. REPLACE THE						
			GASKETS OF RADIATORS, TOP COVER,						
			INSPECTION CO						
			VER, DRAINVALVE, ALL BUSHINGS, PRV ETC.						
			RE-TANK THE CORE AND COIL ASSEMBLY AND						
			FIXTHE TOP COVER WITH ALL THE						
			ACCESSORIES.10. RE-FILL						
			THE SAME OIL. VENDOR HAS TO INFORM DEWA IF						
			THEY NEED OIL,OIL WILL BE ARRANGED BY DEWA						
			IF EXTRA REQUIRED.11. CONDUCT PRESSURE						
			TEST B						
			Y APPLYING NITROGEN PRESSURE FOR 24 HOURS						
			TOCHECK OIL LEAKAGE.12. HOT OIL CIRCULATION						
			TO EXPEL MOISTURE AND IMPROVE BDV.13. TAKE		1				



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			OIL						
			SAMPLE AND DO BDV & MOISTURE TEST AND						
			CONDUCT ROUTINE TESTSAS PER IEC 60076.						
			GENERAL CLEANING.14. LOAD THE TRANSFORMER						
			ON ETS ARRA						
			NGED TRAILER (UNLOADING AT SITE TOBE						
			ARRANGED BY CUSTOMER).16. OIL FOR TOPPING						
			UP (IF REQUIRED) SHALL BE EXTRA. TAKING OUT						
			FROMFOUN						
			DATION AND RE-POSITIONING, LOADING AND						
			UNLOADING OF TRANSFORMER ATDEWA PS SHALL						
			BE ARRANGED BY DEWA.17. CABLE						
			DISCONNECTION, RE-CONN						
			ECTION & TERMINATION SHALL BE DONE						
			BYCUSTOMER (ALL CABLE WORK SHALL BE AT						
			YOUR END).18. CABLE GLANDS & CABLE LUGS,						
			INSULATION BOOTS						
			ARE NOT IN OUR SCOPE.19. NO CIVIL WORK IS						
			CONSIDERED.20. TRANSPORTATION OF						
			TRANSFORMER FROM CUSTOMER SITE TO						
			VENDORS FACTORYSHALL BE						
			DONE BY THE CONTRACTOR. CONTRACTOR HAS						
			TO ARRANGE INSURANCESTARTING FROM		1				





RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

CLOSING DATE : 26.03.2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			COLLECTION OF TRANSFORMER FROM DEWA, WHILE TRANSPORT (TOA ND FRO), SERVICE AT VENDORS WORKSHOP TILL RETURN BACK TO DEWA.21. ALL GATE PASSES / SECURITY PASSES SHALL BE ARRANGED BY DEWA.						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Overhauling

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.



RFQ NUMBER : 2332500739

DATE : 19.03.2025

REQ No : 1032501307

REQ TITLE : Overhauling 1032501307

DELIVERY LOCATION

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP