

**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	RECTIFY VFD DEFECTS AND REPLACESUBSTATION NAME - MSTANOD: 420564465UNIT DETAILS:SAP EQUIPMENT NUMBER - 30346757MAKE: CARRIERMODEL: 3 GBJPH63LJB91K-7AIR HANDLING UNIT AHX 3SERIAL NUMBER - SMAH08167241SUBSTATION # MSTA 400 KV SSSCOPE OF WORK:1.######## VFD DEFECTS TO BE CHECKED & RECTIFY/REPLACE IF NEEDED FORAIR HANDLING UNIT NUMBER 3.2.######## ENSURE THE VFD IS 100 PERCENT FUNCTIONAL AND T HE AHU UNITSETTING IS SYNCHRONIZED WITH THE VFD.3.######## ALL ASSOCIATED DEFECTS SHALL BE RECTIFIED BY THE CONTRACTORAND REINSTAT E THE UNIT BACK TO NORMAL WORKING CONDITIONS.NOTES: THE CONTRACTOR SHALL GIVE MINIMUM 1 YEAR WARRANTY FORWORKMANSHIP AND MATERIAL S UPPLY.FOR PTW APPLICATION, PLEASE SEND MAIL TO: PTW.TCM@DEWA.GOV.AECONTACT PERSON FOR SITE VISIT MR RASHID KALL FRY SR		EA				PRIOE
			FOR SITE VISIT:MR. RASHID KALLERY, SR. ENGINEER- E						



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			LECTROMECH. MAINT. (MOB: 0525507585)PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 1 YEAR OF P ORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AN D SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR A FTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
2		ITEM-00001	RECTIFY VFD DEFECTS AND REPLACESUBSTATION NAME - MSTANOD: 420564465UNIT DETAILS:SAP EQUIPMENT NUMBER - 30346757MAKE: CARRIERMODEL: 3 GBJPH63LJB91K-7AIR HANDLING UNIT AHX 3SERIAL NUMBER - SMAH08167241SUBSTATION # MSTA 400 KV SSSCOPE OF WORK:1.####BLOWER BEARING DEF	1	EA				



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ECTS SHALL BE RECTIFIED AND NSURE THE VFD						
			IS100 PERCENT FUNCTIONAL AND THE AHU UNIT						
			SETTING IS SYNCHRONIZED WITH						
			THEVFD.3.########						
			# ALL ASSOCIATED DEFECTS SHALL BE RECTIFIED						
			BY THE CONTRACTORAND REINSTATE THE UNIT						
			BACK TO NORMAL WORKING CONDITIONS.NOTES :						
			THE CO						
			NTRACTOR SHALL GIVE MINIMUM 1 YEAR						
			WARRANTY FORWORKMANSHIP AND MATERIAL						
			SUPPLY.FOR PTW APPLICATION, PLEASE SEND						
			MAIL TO: PTW.TCM@DEW						
			A.GOV.AECONTACT PERSON FOR SITE VISIT:MR.						
			RASHID KALLERY, SR. ENGINEER- ELECTROMECH.						
			MAINT. (MOB: 0525507585)PAYMENT TERMS AND						
			CONDI TIONS:PENALTY: THE CONTRACTOR SHALL						
			COMPLETE THIS WORK WITHIN 1 YEAR OF						
			PORELEASE DATE, IF THE WORK IS DELAYED						
			BEYOND THAT THEN; DEW						
			A IS ENTITLEDTO A REDUCTION IN THE PO VALUE						
			BY 1.25% PER WEEK OF DELAY AND SUBJECT						
			TOMAXIMUM 10% OF PO VALUE.RETENTION						



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

**REQ TITLE** : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEAS ED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
3		ITEM-00002	RECTIFY VFD DEFECTS AND REPLACESUBSTATION NAME - MSTA 400KVNOD: 420564464UNIT DETAILS:SAP EQUIPMENT NUMBER - 30346755MAKE: CARRIERMO DEL: 3GBJPH63LJB91K-7AIR HANDLING UNIT AHX 1SERIAL NUMBER - SMAH08167278SUBSTATION # MSTA 400 KV SSSCOPE OF WORK:1.######## VFD DE FECTS TO BE CHECKED & RECTIFY/REPLACE IF NEEDED FORAIR HANDLING UNIT NUMBER 1.2. ENSURE THE VFD IS FULLY FUNCTIONAL WITH T HE AHU AND SETTINGHAS TO BE DONE AS PER SITE REQUIREMENTS.3.######### ALL ASSOCIATED DEFECTS SHALL BE RECTIFIED BY THE CONTRACTORAN D REINSTATE THE UNIT BACK TO NORMAL	1	EA				



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			WORKING CONDITIONS.NOTES: THE CONTRACTOR						
			SHALL GIVE MINIMUM 1 YEAR WARRANTY						
			FORWORKMANSHIP AND						
			MATERIAL SUPPLY.FOR PTW APPLICATION,						
			PLEASE SEND MAIL TO:						
			PTW.TCM@DEWA.GOV.AECONTACT PERSON FOR						
			SITE VISIT:MR. RASHID KALLERY, SR. E						
			NGINEER- ELECTROMECH. MAINT. (MOB:						
			0525507585)PAYMENT TERMS AND						
			CONDITIONS:PENALTY: THE CONTRACTOR SHALL						
			COMPLETE THIS WORK WITHIN 1						
			YEAR OF PORELEASE DATE, IF THE WORK IS						
			DELAYED BEYOND THAT THEN; DEWA IS						
			ENTITLEDTO A REDUCTION IN THE PO VALUE BY						
			1.25% PER WEEK O						
			F DELAY AND SUBJECT TOMAXIMUM 10% OF PO						
			VALUE.RETENTION AMOUNT: 5% OF THE TOTAL						
			VALUE OF THE PO WILL BE KEPT AS ARETENTION						
			AMOUNT FO						
			R 1 YEAR AFTER THE COMPLETION CERTIFICATE IS						
			ISSUED,IT WILL BE RELEASED TO THE						
			CONTRACTOR UPON CLEARING ALL RELATED						
			NODS.						



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
4		ITEM-00002	BEARING DEFECTS SHALL BE	1	EA				
			RECTIFIEDSUBSTATION NAME - MSTA 400KVNOD:						
			420564464UNIT DETAILS:SAP EQUIPMENT NUMBER						
			- 30346755MAKE: CARRIE						
			RMODEL: 3GBJPH63LJB91K-7AIR HANDLING UNIT						
			AHX 1SERIAL NUMBER -						
			SMAH08167278SUBSTATION # MSTA 400 KV						
			SSSCOPE OF WORK:1.##### BEARING						
			DEFECTS SHALL BE RECTIFIED AND ENSURE THE						
			VFD IS FULLYFUNCTIONAL WITH THE AHU AND						
			SETTING HAS TO BE DONE AS PER						
			SITEREQUIREMENTS.3.						
			######### ALL ASSOCIATED DEFECTS SHALL BE						
			RECTIFIED BY THE CONTRACTORAND REINSTATE						
			THE UNIT BACK TO NORMAL WORKING						
			CONDITIONS.NOTES						
			: THE CONTRACTOR SHALL GIVE MINIMUM 1 YEAR						
			WARRANTY FORWORKMANSHIP AND MATERIAL						
			SUPPLY.FOR PTW APPLICATION, PLEASE SEND						
			MAIL TO: PT						
			W.TCM@DEWA.GOV.AECONTACT PERSON FOR						
			SITE VISIT:MR. RASHID KALLERY, SR. ENGINEER-						
			ELECTROMECH. MAINT. (MOB:						



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

**REQ TITLE** : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			0525507585)PAYMENT TERMS AND CONDITIONS:PENALTY: THE CONTRACTOR SHALL COMPLETE THIS WORK WITHIN 1 YEAR OF PORELEASE DATE, IF THE WORK IS DELAYED BEYOND THAT THEN; DEWA IS ENTITLEDTO A REDUCTION IN THE PO VALUE BY 1.25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOU NT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NODS.						
5		ITEM-00003	RECTIFY VFD DEFECTS AND REPLACESUBSTATION NAME - MSTA 400KVNOD: 420564463UNIT DETAILS:SAP EQUIPMENT NUMBER - 30346754MAKE: CARRIERMO DEL: 3GAHNH83LJA91L-7AIR HANDLING UNIT AHX 2SERIAL NUMBER - SMAH08167240SUBSTATION # MSTA 400 KV SSSCOPE OF WORK:1.######## VFD DE FECTS TO BE CHECKED & RECTIFY/REPLACE IF	1	EA				



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			NEEDED FORAIR HANDLING UNIT NUMBER						
			2.2.######## ENSURE THE VFD IS FULLY						
			FUNCTIONAL AND AH						
			U UNIT IS WORKINGCONSIDERING THE VFD						
			SETTINGS AS PER SITE						
			REQUIREMENTS.3.######## ALL ASSOCIATED						
			DEFECTS SHALL BE RECTIFIED BY THE						
			CONTRACTORAND REINSTATE THE UNIT BACK TO						
			NORMAL WORKING CONDITIONS.NOTES : THE						
			CONTRACTOR SHALL GIVE MINIMUM 1 YEARS						
			WARRANTY FORWO						
			RKMANSHIP AND MATERIAL SUPPLY.FOR PTW						
			APPLICATION, PLEASE SEND MAIL TO:						
			PTW.TCM@DEWA.GOV.AECONTACT PERSON FOR						
			SITE VISIT:MR. RASHID						
			KALLERY, SR. ENGINEER- ELECTROMECH. MAINT.						
			(MOB: 0525507585)PAYMENT TERMS AND						
			CONDITIONS:PENALTY: THE CONTRACTOR SHALL						
			COMPLETE THIS						
			WORK WITHIN 1 YEAR OF PORELEASE DATE, IF						
			THE WORK IS DELAYED BEYOND THAT THEN;						
			DEWA IS ENTITLEDTO A REDUCTION IN THE PO						
			VALUE BY 1.		1				



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

**REQ TITLE** : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			25% PER WEEK OF DELAY AND SUBJECT TOMAXIMUM 10% OF PO VALUE.RETENTION AMOUNT: 5% OF THE TOTAL VALUE OF THE PO WILL BE KEPT AS ARETEN TION AMOUNT FOR 1 YEAR AFTER THE COMPLETION CERTIFICATE IS ISSUED,IT WILL BE RELEASED TO THE CONTRACTOR UPON CLEARING ALL RELATED NO DS.						
6		ITEM-00003	REPLACE/RECTIFY BLOWER MOTOR DEFECTSSUBSTATION NAME - MSTA 400KVNOD: 420564463UNIT DETAILS:SAP EQUIPMENT NUMBER - 30346754MAKE: CARR IERMODEL: 3GAHNH83LJA91L-7AIR HANDLING UNIT AHX 2SERIAL NUMBER - SMAH08167240SUBSTATION # MSTA 400 KV SSSCOPE OF WORK:1.#BLOWER MOTO R SHALL BE REPLACED AND ENSURE THE VFD IS FULLY FUNCTIONALAND AHU UNIT IS WORKING CONSIDERING THE VFD SETTINGS AS PER SITEREQUIREMEN TS.2.ALL ASSOCIATED DEFECTS SHALL BE RECTIFIED BY THE CONTRACTOR ANDREINSTATE	1	EA				



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			THE UNIT BACK TO NORMAL WORKING						
			CONDITIONS.NOTES: THE						
			CONTRACTOR SHALL GIVE MINIMUM 1 YEARS						
			WARRANTY FORWORKMANSHIP AND MATERIAL						
			SUPPLY.FOR PTW APPLICATION, PLEASE SEND						
			MAIL TO: PTW.TCM						
			@DEWA.GOV.AECONTACT PERSON FOR SITE						
			VISIT:MR. RASHID KALLERY, SR. ENGINEER-						
			ELECTROMECH. MAINT. (MOB:						
			0525507585)PAYMENT TERMS AND C						
			ONDITIONS:PENALTY: THE CONTRACTOR SHALL						
			COMPLETE THIS WORK WITHIN 1 YEAR OF						
			PORELEASE DATE, IF THE WORK IS DELAYED						
			BEYOND THAT THEN;						
			DEWA IS ENTITLEDTO A REDUCTION IN THE PO						
			VALUE BY 1.25% PER WEEK OF DELAY AND						
			SUBJECT TOMAXIMUM 10% OF PO						
			VALUE.RETENTION AMOUNT: 5						
			% OF THE TOTAL VALUE OF THE PO WILL BE KEPT						
			AS ARETENTION AMOUNT FOR 1 YEAR AFTER THE						
			COMPLETION CERTIFICATE IS ISSUED,IT WILL BE						
			RE						
			LEASED TO THE CONTRACTOR UPON CLEARING						



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

**CLOSING DATE** : 16.07.2025

**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ALL RELATED NODS.						

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

#### **SPECIAL NOTES / INSTRUCTIONS:**

Rectify AHU-2 VFD defects @ MSTA 400kVContact person for site visit:Mr. Rashid Kallery, Sr. Engineer- Electromech. maint. (Tel. 04-3 221477,Mob: 055-9419528)

#### **STANDARD TERMS & CONDITIONS**

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.



**RFQ NUMBER** : 2332501688

**DATE** : 07.07.2025

**REQ No** : 1032503196

REQ TITLE : 1032503214:Rectify & Replace

**DELIVERY LOCATION** 

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP