

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2332501689  
**DATE** : 07.07.2025  
**REQ No** : 1032503141  
**REQ TITLE** : 1032503175 77 78 41 Eng Leak  
**DELIVERY LOCATION**  
**CLOSING DATE** : 16.07.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	LEAK REPAIR OF ENGINE COOLING LINE IN ODMT 132 KV SUBSTATION.ISSUE: LEAK REPORTED IN ENGINE COOLING LOOP PIPE FITTINGS.CLARKE; IVE CO FIAT;SUPPLY OF SPARES, INSTALLATION AND TESTING TO BE INCLUDED IN SCOPE. PUMPTO BE TESTED SUCCESSFULLY AFTER COMPLETIONFOR FURTHER TECHNICAL DETAILS AND SITE VISIT, PLEASE CONTACT ENGR.NARAYANASAMY , 058-8908575 , NARAYANASAMY.RAMASAM@DEWA.GOV.AEOTHER ENQUIRES, CONTACT ENGR. ANEEZ HUSSAIN , 04-3221323 ,ANEEZ.ABDULRAZAK@DEWA.GOV.AE	1	AU				
2		ITEM-00002	LEAK REPAIR OF ENGINE COOLING LINE IN KBSI 132 KV SUBSTATION.ISSUE: LEAK REPORTED IN ENGINE COOLING LOOP PIPE FITTINGS.CLARKE; JU6 H-UFM2; PE6068T745119SUPPLY OF SPARES, INSTALLATION AND TESTING TO BE INCLUDED IN SCOPE. PUMPTO BE TESTED SUCCESSFULLY AFTER COMPLETIONFOR FURTHER TECHNICAL DETAILS AND SITE	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2332501689  
**DATE** : 07.07.2025  
**REQ No** : 1032503141  
**REQ TITLE** : 1032503175 77 78 41 Eng Leak  
**DELIVERY LOCATION**  
**CLOSING DATE** : 16.07.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			VISIT, PLEASE CONTACT ENGR.NARAYANASAMY , 058-8908575 , NARAYANASAMY.RAMASAM@DEWA.GOV.AEOT HER ENQUIRES, CONTACT ENGR. ANEEZ HUSSAIN , 04-3221323 ,ANEEZ.ABDULRAZAK@DEWA.GOV.AE						
3		ITEM-00003	ENGINE EXHAUST PIPE DAMAGE REPAIR IN WELNSVLG 132 KV SUBSTATION.ISSUE: EXHAUST GAS LEAK REPORTED IN ENGINE EXHAUST PIPELINE.CLARKE; JU6H-UFM2; DAC/PE6068T960274CONDUCT A THOROUGH INSPECTION OF THE ENGINE EXHAUST PIPELINE TO IDENTIFYTHE SOURCE AND ASSESS THE CONDI TION OF EXHAUST LINE INSULATION FOR HEATDAMAGE, WEAR, OR DEGRADATION.SUPPLY ALL NECESSARY SPARES AND CONSUMABLES, INCLUDING:#EXHAUS T PIPE SECTIONS AND FITTINGS.#GASKETS, SEALS, CLAMPS, AND FLANGES.#HEAT-RESISTANT EXHAUST LINE INSULATION (IF FOUND DAMAGED DURINGIN SPECTION)PERFORM A LEAK TEST AND THERMAL INSPECTION OF THE REPAIRED EXHAUSTSYSTEM.	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2332501689  
**DATE** : 07.07.2025  
**REQ No** : 1032503141  
**REQ TITLE** : 1032503175 77 78 41 Eng Leak  
**DELIVERY LOCATION**  
**CLOSING DATE** : 16.07.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			CONDUCT A FULL OPERATIONAL TEST OF THE PUMP TO CONFIRM SYSTEM PERFORMANCE AND INTEGRITY. SUBMIT SERVICE REPORT WITH LIST OF PARTS REPLACED. FOR FURTHER TECHNICAL DETAILS AND SITE VISIT , PLEASE CONTACT ENGR. NARAYANASAMY , 058-8908575 , NARAYANASAMY.RAMASAM@DEWA.GOV.AE. OTHER ENQUIRES, CONTACT ENGR. ANEEZ HUSSAIN , 04-3221323 , ANEEZ.ABDULRAZAK@DEWA.GOV.AE						
4		ITEM-00004	ENGINE EXHAUST PIPE DAMAGE REPAIR IN THRDNSHB 132 KV SUBSTATION. ISSUE: EXHAUST GAS LEAK REPORTED IN ENGINE EXHAUST PIPELINE. CLARKE; JU4H-UF54; PE 4045E003974. CONDUCT A THOROUGH INSPECTION OF THE ENGINE EXHAUST PIPELINE TO IDENTIFY THE SOURCE AND ASSESS THE CONDITION OF EXHAUST LINE INSULATION FOR HEAT DAMAGE, WEAR, OR DEGRADATION. SUPPLY ALL NECESSARY SPARES AND CONSUMABLES, INCLUDING: #EXHAUST P	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2332501689  
**DATE** : 07.07.2025  
**REQ No** : 1032503141  
**REQ TITLE** : 1032503175 77 78 41 Eng Leak  
**DELIVERY LOCATION**  
**CLOSING DATE** : 16.07.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			IPE SECTIONS AND FITTINGS-#GASKETS, SEALS, CLAMPS, AND FLANGES-#HEAT-RESISTANT EXHAUST LINE INSULATION (IF FOUND DAMAGED DURING INSPECTION) PERFORM A LEAK TEST AND THERMAL INSPECTION OF THE REPAIRED EXHAUST SYSTEM. CONDUCT A FULL OPERATIONAL TEST OF THE PUMP TO CONFIRM SYSTEM PERFORMANCE AND INTEGRITY. SUBMIT SERVICE REPORT WITH LIST OF PARTS REPLACED. FOR FURTHER TECHNICAL DETAILS AND SITE VISIT, PLEASE CONTACT ENGR. NARAYANASAMY , 058-8908575 , NARAYANASAMY.RAMASAM@DEWA.GOV.AE OTHER ENQUIRES, CONTACT ENGR. ANEEZ HUSSAIN , 04-322 1323 , ANEEZ.ABDULRAZAK@DEWA.GOV.AE						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

### SPECIAL NOTES / INSTRUCTIONS:

FPS Diesel Engine repair various sites

MATERIAL AND OR SERVICE PROVIDED TO DEWA SHOULD PREFERABLY BE ENERGY EFFICIENT AND ENVIRONMENT FRIENDLY.

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2332501689  
**DATE** : 07.07.2025  
**REQ No** : 1032503141  
**REQ TITLE** : 1032503175 77 78 41 Eng Leak  
**DELIVERY LOCATION**  
**CLOSING DATE** : 16.07.2025  
**CLOSING TIME** : 10:00:00

### STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

**SUPPLIER'S REMARKS :**

**SUPPLIER'S SIGNATURE AND STAMP**