

RFQ NUMBER : 2332502276

DATE : 10.09.2025

REQ No : 1032504002

REQ TITLE: G station, Desalination plant

DELIVERY LOCATION

CLOSING DATE : 16.09.2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	I AM WRITING TO PROVIDE DETAILED	2	EA				
			INSTRUCTIONS REGARDING THE						
			REPLACEMENTWORK FOR THE DN 1600 METALLIC						
			EXPANSION BELLOW CONVOLUTE.THE						
			CONTRACTOR SHALL COLLECT THE SPARE						
			BELLOW ASSEMBLY FROM DEWA.IT IS ESSENTIAL						
			THAT THE SPARE BELLOW IS STORED PROPERLY						
			AND THEEXISTIN						
			G DAMAGED CONVOLUTE IS REPLACED WITH NEW						
			CONVOLUTES, WHICH WILL CONSIST OF TWO						
			INNER PLIES IN 316L AND AN OUTER PLY						
			ININCONEL 825.THE						
			CONTRACTOR IS REQUIRED TO REUSE THE						
			EXISTING FLANGE AND BODY FROMTHE DEWA						
			SUPPLIED BELLOW.PLEASE NOTE THAT THE						
			CONVOLUTES WILL BE S						
			UPPLIED BY DEWA, ALONG WITH THEFULL						
			ASSEMBLY OF THE EXPANSION BELLOW.THE						
			CONTRACTOR'S RESPONSIBILITY INCLUDES						
			REMOVING THE DAMAGED C						
			ONVOLUTESAND INSTALLING THE NEW						
			ONES,ENSURING THAT ARC WELDING IS NOT						
			USED. ONLY TIG WELDING IS PERMITTED FORTHIS						



RFQ NUMBER : 2332502276

DATE : 10.09.2025

REQ No : 1032504002

REQ TITLE : G station, Desalination plant

DELIVERY LOCATION

CLOSING DATE : 16.09.2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TASK.ADDITIONALLY,						
			ALL CONSUMABLES WILL BE COVERED BY THE						
			CONTRACTOR.AFTER COMPLETING THE WELDING,						
			THE CONTRACTOR MUST CARRY OUT A						
			DYEPENETRANT (DP) T						
			EST ON THE WELDING JOINTS.FOLLOWING THE						
			SUCCESSFUL COMPLETION OF THE DP TEST, A						
			PRESSURE TEST AT 6BAR SHOULD BE						
			CONDUCTED TO ENSURE						
			THE INTEGRITY OF THE INSTALLATION.IN THE						
			EVENT OF ANY CHANGES IN THE FLANGE						
			FACE-TO-FACE DIMENSIONS OR IFTHE FLANGE						
			HOLES ON BOTH EN						
			DS ARE MISALIGNED, THE CONTRACTOR MUST						
			REWORKTO RECTIFY THESE ISSUES.THE						
			TRANSPORTATION OF THE BELLOW WILL BE THE						
			CONTRACTOR'SRESPON						
			SIBILITY.FURTHERMORE, THE CONTRACTOR IS						
			REQUESTED TO VISIT THE SITE TO						
			UNDERSTANDTHE SCOPE AND QUANTUM OF THE						
			JOB INVOLVED. PLEASE E						
			NSURE ALL STEPS ARE FOLLOWED METICULOUSLY						
			TO GUARANTEE THESUCCESSFUL COMPLETION						



RFQ NUMBER : 2332502276

DATE : 10.09.2025

REQ No : 1032504002

REQ TITLE : G station, Desalination plant

DELIVERY LOCATION

CLOSING DATE : 16.09.2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			OF THIS PROJECT. IF YOU HAVE ANY QUESTIONS OR REQUIR E FURTHER CLARIFICATION, DO NOTHESITATE TO REACH OUT MR. MOHAMMAD RAFI (MOHAMMAD.HOSUR@DEWA.GOV.AE)048044964 / 0529740743						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

G station, Desalination plant Brine heater inlet metalic Bellow convolutes replacement.

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.



RFQ NUMBER : 2332502276

DATE : 10.09.2025

REQ No : 1032504002

REQ TITLE : G station, Desalination plant

DELIVERY LOCATION

CLOSING DATE : 16.09.2025 **CLOSING TIME** : 10:00:00

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP