

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2412500231  
**DATE** : 06.02.2025  
**REQ No** : 1032406003  
**REQ TITLE** : 1-Repair of Nitrogen Gas  
**DELIVERY LOCATION**  
**CLOSING DATE** : 14.02.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	REPAIR OF NITROGEN GAS SYSTEM AT CEMENT 132KV SUBSTATIONSAP ORDER: 521363270N2 MAIN BANK CYLINDER-7 LOW PRESSURE MONITOR PRESSURE SW ITCH REPORTEDFAULTY.MAKE: RG SYSTEM SPAIN IG-100SCOPE OF WORK INCLUDES SUPPLY OF SPARES AND REFILLING IF REQUIRED.REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OF SPARES AND REINSTALLINGBACK AT SITE. WARRANTY TO BE PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WE EKS FROM ISSUE OF PO	1	AU				
2		ITEM-00002	REPAIR OF NITROGEN GAS SYSTEM AT CIRCLEX 132KV SUBSTATIONSAP ORDER: 521371495N2 MAIN BANK CYLINDER-11 LOW PRESSURE MONITOR PRESSURE SWITCH REPORTEDFAULTY.MAKE: RG SYSTEM SPAIN IG-100SCOPE OF WORK INCLUDES SUPPLY OF SPARES AND REFILLING IF REQUIRED.REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OF SPARES AND REINSTALLINGBACK AT SITE. WARRANTY TO BE	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2412500231  
**DATE** : 06.02.2025  
**REQ No** : 1032406003  
**REQ TITLE** : 1-Repair of Nitrogen Gas  
**DELIVERY LOCATION**  
**CLOSING DATE** : 14.02.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO						
3		ITEM-00003	REFILLING OF N2 GAS CYLINDERS AT FAYROAD 132KV SUBSTATIONSAP ORDER: 521363277CAPACITOR BANK ROOM-1 RESERVE CARTRIDGE CYLINDER ISSUE. MAKE: SIEX SPAIN IG-100SCOPE OF WORK INCLUDES SUPPLY OF SPARES AND REFILLING IF REQUIRED.REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OF SPARES AND REINSTALLINGBACK AT SITE. WARRANTY TO BE PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO	1	AU				
4		ITEM-00004	REFILLING OF N2 GAS CYLINDERS AT FUNLAND 132KV SUBSTATIONSAP ORDER: 521374387RESERVE CYLINDER NO. 7 (QTY: 1)80L @ 300 BARMAKE: SIEX SPAIN IG-100SCOPE OF WORK INCLUDES REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OF SPARES AND REINSTALLING BACK AT SITE.WARRANTY TO BE P	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2412500231  
**DATE** : 06.02.2025  
**REQ No** : 1032406003  
**REQ TITLE** : 1-Repair of Nitrogen Gas  
**DELIVERY LOCATION**  
**CLOSING DATE** : 14.02.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO						
5		ITEM-00005	REFILLING OF N2 GAS CYLINDERS AT GRDNTOWR 132KV SUBSTATIONSAP ORDER: 521196987RESERVE CYLINDER NO. 12 (QTY: 1)80L @ 300 BARMAKE: SIE X SPAIN IG-100SCOPE OF WORK INCLUDES REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OFSPARES AND REINSTALLING BACK AT SITE. REFILLING CER TIFICATE TO BEPROVIDED.WARRANTY TO BE PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO	1	AU				
6		ITEM-00006	REPAIR OF NITROGEN GAS SYSTEM AT MDNAETMR 132KV SUBSTATIONSAP ORDER: 521362555N2 RESERVE BANK CYLINDER-12 LOW PRESSURE MONITOR PRESS URE SWITCHREPORTED FAULTY.MAKE: RG SYSTEM SPAIN IG-100SCOPE OF WORK INCLUDES SUPPLY OF SPARES AND REFILLING IF REQUIRED.REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OF SPARES AND REINSTALLINGBACK AT SITE. WARRANTY TO BE	1	AU				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2412500231  
**DATE** : 06.02.2025  
**REQ No** : 1032406003  
**REQ TITLE** : 1-Repair of Nitrogen Gas  
**DELIVERY LOCATION**  
**CLOSING DATE** : 14.02.2025  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO						
7		ITEM-00007	MUSHPARK-REFILL SIEX SPAIN N2 CYLINDER	1	AU				
8		ITEM-00008	REFILLING OF N2 GAS CYLINDERS AT DXBHILS 132KV SUBSTATIONSAP ORDER: 521369139RESERVE CYLINDER NO. 5 (QTY: 1)80L @ 300 BARMAKE: SIEX SPAIN IG-100SCOPE OF WORK INCLUDES REMOVAL FROM SITE, TRANSPORTATION, SUPPLY OFSPARES AND REINSTALLING BACK AT SITE. REFILLING CERTIFICATE TO BE PROVIDED.WARRANTY TO BE PROVIDED FOR 6 MONTHSWORK TO BE COMPLETED WITHIN 2 WEEKS FROM ISSUE OF PO	1	AU				

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

**SPECIAL NOTES / INSTRUCTIONS:**

Note to LPD:Requested to club the below PRs as single Rfx

**STANDARD TERMS & CONDITIONS**

1) Prices should be 'DDP' delivery duty paid at DEWA stores.

**MATERIAL AND OR SERVICE PROVIDED TO DEWA SHOULD PREFERABLY BE ENERGY EFFICIENT AND ENVIRONMENT FRIENDLY.**

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2412500231  
**DATE** : 06.02.2025  
**REQ No** : 1032406003  
**REQ TITLE** : 1-Repair of Nitrogen Gas  
**DELIVERY LOCATION**  
**CLOSING DATE** : 14.02.2025  
**CLOSING TIME** : 10:00:00

- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

**SUPPLIER'S REMARKS :**

**SUPPLIER'S SIGNATURE AND STAMP**