

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	URGENT REPAIR OF ENGINE STARTER AT BBAYCREK 132KV SUBSTATION.ISSUE: STARTER MOTOR FOUND FAULTY.MAKE: DEUTZ ; MODEL: DFP6-2012-C10 ; SERIAL # 11229448INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INST ALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING ULIFM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW A ND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ. ABDULRAZAK@DEWA.GOV.AE, 04-3221323,	1	AU				
2		ITEM-00002	URGENT REPAIR OF ENGINE STARTER AT BRES 132KV SUBSTATION.ISSUE: STARTER MOTOR	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			FOUND FAULTY. TACH HOUR METER NOT WORKINGMAKE: CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PE-6068T673115INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
3		ITEM-00003	REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT DLVL 132KVSUBSTATION.ISSUE:	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TACH HOUR METER / RPM METER FOUND DEFECTIVE.MAKE : CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PE-6068T661687INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUD ES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECE IPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE OWN FACILITY FOR REPAIR AND SERVICING. O NLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUI RIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
4		ITEM-00004	REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT TCRA	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KVSUBSTATION.ISSUE: TACH HOUR METER / RPM METER FOUND DEFECTIVE.MAKE : CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PF6068T759748SAP WORK ORDER # 521156774INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE OWN FACILITY FO R REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 0 4-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
5		ITEM-00005	REPLACEMENT OF FUEL GAUGE IN FIRE DIESEL	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE AT OXYGEN 132KVSUBSTATION.ISSUE: DIESEL ENGINE FUEL GAUGE FOUND FAULTYMAKE: CLARKE; MODEL: JU6H-UF30 ; SERIAL # PE6068E001175INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY O F NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VE NDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WI LL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT E NGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
6		ITEM-00006	URGENT REPAIR OF FIRE DIESEL ENGINE AT TJTN	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE SHOWING HIGH TEMPERATUREMAKE: CLARKE; MODEL: JU6H-UFM2; SERIAL # PE6068T767207INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY S PARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTE D.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HU SAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
7		ITEM-00007	URGENT REPAIR OF FIRE DIESEL ENGINE AT KHILROAD 132KV SUBSTATION.ISSUE: DIESEL	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE EXHAUST PIPE OUTSIDE FLAPPER DAMAGED.MAKE: CLA RKE; MODEL: JU6H-UF52; SERIAL # PE6068E000980INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE ACCEPTED. HIGH LEVEL ACCESS ARRANGEMENT ISCONTRACTOR SCOPEFOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,S RIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
8		ITEM-00008	URGENT REPAIR OF FIRE DIESEL ENGINE AT WTSC	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE GAUGE PANEL RECTIFIER FOUND.MAKE: CLARKE; MODEL: J U6H-UFG8 ; SERIAL # PE6068T794934INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
9		ITEM-00009	URGENT REPAIR OF FIRE DIESEL ENGINE AT DSOS	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE COOLING LINE DAMAGEDMAKE: CLARKE; MODEL: JU6H-UFM2 ; SERIAL # PF6068T745112INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARE S, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPE RIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE A CCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. AN EEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

MATERIAL AND OR SERVICE PROVIDED TO DEWA SHOULD PREFERABLY BE ENERGY EFFICIENT AND ENVIRONMENT FRIENDLY.

Page9 of 10

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	URGENT REPAIR OF ENGINE STARTER AT BBAYCREK 132KV SUBSTATION.ISSUE: STARTER MOTOR FOUND FAULTY.MAKE: DEUTZ ; MODEL: DFP6-2012-C10 ; SERIAL # 11229448INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INST ALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING ULIFM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW A ND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ. ABDULRAZAK@DEWA.GOV.AE, 04-3221323,	1	AU				
2		ITEM-00002	URGENT REPAIR OF ENGINE STARTER AT BRES 132KV SUBSTATION.ISSUE: STARTER MOTOR	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			FOUND FAULTY. TACH HOUR METER NOT WORKINGMAKE: CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PE-6068T673115INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
3		ITEM-00003	REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT DLVL 132KVSUBSTATION.ISSUE:	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TACH HOUR METER / RPM METER FOUND DEFECTIVE.MAKE : CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PE-6068T661687INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUD ES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECE IPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE OWN FACILITY FOR REPAIR AND SERVICING. O NLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUI RIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
4		ITEM-00004	REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT TCRA	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KVSUBSTATION.ISSUE: TACH HOUR METER / RPM METER FOUND DEFECTIVE.MAKE : CLARKE; MODEL: JU6H-UFG8 ; SERIAL # PF6068T759748SAP WORK ORDER # 521156774INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE OWN FACILITY FO R REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 0 4-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
5		ITEM-00005	REPLACEMENT OF FUEL GAUGE IN FIRE DIESEL	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE AT OXYGEN 132KVSUBSTATION.ISSUE: DIESEL ENGINE FUEL GAUGE FOUND FAULTYMAKE: CLARKE; MODEL: JU6H-UF30 ; SERIAL # PE6068E001175INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY O F NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VE NDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WI LL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT E NGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
6		ITEM-00006	URGENT REPAIR OF FIRE DIESEL ENGINE AT TJTN	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE SHOWING HIGH TEMPERATUREMAKE: CLARKE; MODEL: JU6H-UFM2; SERIAL # PE6068T767207INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY S PARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTE D.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HU SAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
7		ITEM-00007	URGENT REPAIR OF FIRE DIESEL ENGINE AT KHILROAD 132KV SUBSTATION.ISSUE: DIESEL	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE EXHAUST PIPE OUTSIDE FLAPPER DAMAGED.MAKE: CLA RKE; MODEL: JU6H-UF52; SERIAL # PE6068E000980INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE ACCEPTED. HIGH LEVEL ACCESS ARRANGEMENT ISCONTRACTOR SCOPEFOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,S RIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
8		ITEM-00008	URGENT REPAIR OF FIRE DIESEL ENGINE AT WTSC	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE GAUGE PANEL RECTIFIER FOUND.MAKE: CLARKE; MODEL: J U6H-UFG8 ; SERIAL # PE6068T794934INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
9		ITEM-00009	URGENT REPAIR OF FIRE DIESEL ENGINE AT DSOS	1	AU				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE COOLING LINE DAMAGEDMAKE: CLARKE; MODEL: JU6H-UFM2 ; SERIAL # PF6068T745112INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARE S, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPE RIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE A CCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. AN EEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2412501499
DATE : 17.09.2025
REQ No : 1032503597
REQ TITLE : Urgent repair 1032503676
DELIVERY LOCATION
CLOSING DATE : 26.09.2025
CLOSING TIME : 10:00:00

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP