

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT BIRD 132 KV SS SECURITY ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: PART OF ASSET NO. 125000000195 SAP EQPT NO.: 30348248)	1	EA				
2	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2 TR AT DADM 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER:NA SAP EQPT NO.: 30348407)						
3	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT DMCY 132 KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: NA SAP EQPT NO.: 30348459)	1	EA				
4	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2 TR AT KNLG 132 KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UN IT ASSET NUMBER: 121000005140 SAP EQPT NO.: 30348959)						
5	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2 TR AT KNLG 132 KV SS ACCOMMODATION AND T O REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UN IT ASSET NUMBER: 121000005139 SAP EQPT NO.: 30348960)	1	EA				
6	7000000011		SUPPLY, INSTALLATION, TESTING AND	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT ENPO 400 KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004342 SAP EQPT NO.: 30348565)						
7	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT ENPO 400 KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004343 SAP EQPT NO.: 30348566)						
8	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT HRSR 400 KV SS SECURITY ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004636 SAP EQPT NO.: 30348766)	1	EA				
9	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT MBCH 400 KV SS SECURITY ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004509 SAP EQPT NO.: 30349024)						
10	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 1.5 TR AT TCGY 400 KV SS SECURITY ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004565 SAP EQPT NO.: 30349469)	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
11	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2.5 TR AT BRR1 132 KV SS ACCOMMODATION-1 A ND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING A C UNIT ASSET NUMBER: 189885 SAP EQPT NO.: 30348300)	1	EA				
12	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2.5 TR AT BRR1 132 KV SS ACCOMMODATION-2 A ND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING A C UNIT ASSET NUMBER: 189884 SAP EQPT NO.: 30348301)						
13	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2.5 TR AT CNST 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 189960 SAP EQPT NO.: 30348390)	1	EA				
14	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2.5 TR AT JDAF 132 KV SS FIRE PUMP ROOM	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492300341
DATE : 20.06.2023
REQ No : 1172300193
REQ TITLE : installation,testing 1172300193
DELIVERY LOCATION
CLOSING DATE : 26.06.2023
CLOSING TIME : 10:00:00

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

installation,testing

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP