

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT HLDY 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000003379 SAP EQPT NO.: 30348747)	1	EA				
2	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT JARA 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC U NIT ASSET NUMBER: 600083 SAP EQPT NO.: 30348883)						
3	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT KFAF 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC U NIT ASSET NUMBER: PART OF ASSET NO. 1250000000194 SAP EQPT NO.: 30348940)	1	EA				
4	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT KFAF 132 KV SS FIRE PUMP ROOM AND	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: PART OF ASSET NO. 125000000194 SAP EQPT NO.: 30348941)						
5	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT ODMT 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 183789 SAP EQPT NO.:	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			30349261)						
6	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT SKLN 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: PART OF ASSET NO. 1250000000191 SAP EQPT NO.: 30349422)	1	EA				
7	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT SPCB 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			E DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC U NIT ASSET NUMBER: 183773 SAP EQPT NO.: 30349433)						
8	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT WTSC 132 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC U NIT ASSET NUMBER: NA SAP EQPT NO.: 30349558)	1	EA				
9	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT SRSDM 400 KV SS FIRE PUMP ROOM AND	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004445 SAP EQPT NO.: 30349443)						
10	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT SRS LG 400 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004436 SAP EQPT	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			NO.: 30349447)						
11	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT SRSML 400 KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004427 SAP EQPT NO.: 30349451)	1	EA				
12	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT ARSD 132 KV SS FIRE PUMP ROOM	1	EA				
13	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT PILT 132 KV SS FIRE PUMP ROOM	1	EA				

## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
14	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 3 TR AT LOGS 132 KV SS FIRE PUMP ROOM	1	EA				

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

### SPECIAL NOTES / INSTRUCTIONS:

Supply, installation,

### STANDARD TERMS & CONDITIONS

- Prices should be 'DDP' delivery duty paid at DEWA stores.
- Quotation to be submitted only in local currency U.A.E Dirhams
- DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.



## REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

**RFQ NUMBER** : 2492300476  
**DATE** : 13.09.2023  
**REQ No** : 1172300459  
**REQ TITLE** : Supply, installation, 1172300459  
**DELIVERY LOCATION**  
**CLOSING DATE** : 21.09.2023  
**CLOSING TIME** : 10:00:00

**SUPPLIER'S REMARKS :**

**SUPPLIER'S SIGNATURE AND STAMP**