

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT CPTI 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 189913 SAP EQPT NO.: 30348392)	1	EA				
2	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT ENPO 400KV SS ACCOMMODATION AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 121000004342 SAP EQPT NO.: 30348565)						
3	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT ENPO 400KV SS ACCOMMODATION AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 121000004343 SAP EQPT NO.: 30348566)	1	EA				
4	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT IPRK 132KV SS NITROGEN ROOM AND T	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT SAP EQPT NO.: 30763506)						
5	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT JAIN 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 121000005805 SAP EQPT NO.: 30348882)	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
6	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT KTJR 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 600174 SAP EQPT NO.: 30348966)	1	EA				
7	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT LOGS 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT SAP EQPT NO.: 30348989)						
8	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT MCLB 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT ASSET NUMBER: PART OF ASSET NO. 1250000000192 SAP EQPT NO.: 30349033)	1	EA				
9	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT SKLN 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: PART OF ASSET NO. 125000000191 SAP EQPT NO.: 30349421)						
10	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT TCGY 400KV SS ACCOMMODATION-2 AND TOREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT A C UNITASSET NUMBER: 121000004567 SAP EQPT NO.: 30349471)	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
11	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT TCRA 132KV SS SECURITY ROOM AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 600300 SAP EQPT NO.: 30349474)	1	EA				
12	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT TCRA 132KV SS ACCOMMODATION AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 600302 SAP EQPT NO.: 30349476)						
13	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 1.5 TR AT WSLR 132KV SS ACCOMMODATION AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT SAP EQPT NO.: 30349557)	1	EA				

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Split Unit A/C

MATERIAL AND OR SERVICE PROVIDED TO DEWA SHOULD PREFERABLY BE ENERGY EFFICIENT AND ENVIRONMENT FRIENDLY.

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400150
DATE : 13.03.2024
REQ No : 1172400019
REQ TITLE : Split Unit A/C 1172400019
DELIVERY LOCATION
CLOSING DATE : 19.03.2024
CLOSING TIME : 10:00:00

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP