

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT HTEC 132KV SS ACCOMMODATION AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT SAP EQPT NO.: 30348782)	1	EA				
2	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT JARA 132KV SS SECURITY ROOM AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UN ITASSET NUMBER: 600085 SAP EQPT NO.: 30348885)						
3	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT JHRC 132KV SS SECURITY ROOM AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UN ITASSET NUMBER: PART OF ASSET NO. 125000000218 SAP EQPT NO.: 30348905)	1	EA				
4	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT KHLS 132KV SS SECURITY ROOM AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT) IT ASSET NUMBER: 900130 SAP EQPT NO.: 30348948)						
5	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT KTJR 132KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT) IT ASSET NUMBER: 600175 SAP EQPT NO.: 30348967)	1	EA				
6	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT KTJR 132KV SS	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ACCOMMODATION AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFE CTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UN ITASSET NUMBER: 600176 SAP EQPT NO.: 30348968)						
7	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT LSTC 132KV SS SECURITY ROOM AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFE CTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UN ITASSET NUMBER: 600237 SAP EQPT NO.: 30348994)	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
8	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT SDJZ 132KV SS SECURITY ROOM AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 900139 SAP EQPT NO.: 30349405)	1	EA				
9	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT SDJZ 132KV SS ACCOMMODATION-1 AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 900140 SAP EQPT NO.: 30349406)						
10	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT SDJZ 132KV SS ACCOMMODATION-2 AND T OREPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHEDSPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THEDE FECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP ITAT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNITASSET NUMBER: 900141 SAP EQPT NO.: 30349407)	1	EA				
11	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT SZRT 132KV SS FIRE PUMP ROOM AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT ASSET NUMBER: 189997 SAP EQPT NO.: 30349464)						
12	7000000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE WALL MOUNTED SPLIT AC UNIT. 2 TR AT SZRT 132KV SS ACCOMMODATION AND TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT ASSET NUMBER: 189999 SAP EQPT NO.: 30349465)	1	EA				
13	7000000011		SUPPLY, INSTALLATION, TESTING AND	1	EA				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			COMMISSIONING OF DECORATIVE WALLMOUNTED SPLIT AC UNIT. 2 TR AT SZRT 132KV SS ACCOMMODATION AND TOR EPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING SPLIT AC UNIT ASSET NUMBER: 190000 SAP EQPT NO.: 30349466)						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Split A/C Units

STANDARD TERMS & CONDITIONS

- Prices should be 'DDP' delivery duty paid at DEWA stores.
- Quotation to be submitted only in local currency U.A.E Dirhams

MATERIAL AND OR SERVICE PROVIDED TO DEWA SHOULD PREFERABLY BE ENERGY EFFICIENT AND ENVIRONMENT FRIENDLY.

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2492400421
DATE : 23.07.2024
REQ No : 1172400475
REQ TITLE : Split A/C Units 1172400475
DELIVERY LOCATION
CLOSING DATE : 29.07.2024
CLOSING TIME : 10:00:00

3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material

4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.

5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP